# CERCLA OFFSITE DISPOSAL REPORT CADIE AUTO SALVAGE SITE EMERGENCY AND RAPID RESPONSE SERVICES REGION 5

#### Prepared for:

U.S. Environmental Protection Agency Region 5 77 W. Jackson Boulevard Chicago, IL 60604

> EPA Contract No. EP-S5-08-02 Task Order No. 0067

> > Prepared by:

Environmental Quality Management, Inc. 1800 Carillon Boulevard Cincinnati, OH 45240

December 27, 2011

## **TABLE OF CONTENTS**

<u>Section</u>		<u>Page</u>
1.0	Introduction and Overview	1
2.0	CERCLA Offsite Disposal Reports	2

#### 1.0 INTRODUCTION AND OVERVIEW

This report was prepared by Environmental Quality Management, Inc. (EQ), in accordance with Section F.2.2.C of EQ's Emergency and Rapid Response Services Contract No. EP-S5-08-02. The report summarizes all off-site disposal activities for the following task order site:

Superfund Site Name:

Cadie Auto Salvage Site

State:

Illinois

**CERCLIS Number:** 

ILR000164475

Section 2.0 is a compilation of site specific CERCLA Off-Site Disposal Reports for each waste stream that was identified, characterized, and disposed of at off-site treatment, storage, or disposal facilities.

#### 2.0 CERCLA OFF-SITE DISPOSAL REPORTS

This section contains site specific CERCLA Off-Site Disposal Reports for each waste stream that was identified, characterized, and disposed of at off-site treatment, storage, or disposal facilities. A total of eleven (11) waste streams were identified as follows for the Cadie Auto Salvage site:

	Waste Stream No.	Type/Form
1.	Flammable Liquids	Solvents/Liquid Waste
2.	RCRA Empty Containers	Non-Hazardous/Contaminated Soil and Debris
3.	Soil	Non-Hazardous/Contaminated Soil and Debris
4.	Virgin Products and Soil	Non-Hazardous/Contaminated Soil and Debris
5.	Lithium Hydride	Other RCRA-listed Hazardous Wastes/ Solid or Solidified Waste
6.	Ceric Sulfate	Non-Hazardous/Solid or Solidified Waste
7.	Sodium Hydroxide	Non-Hazardous/Solid or Solidified Waste
8.	Paint	Solvents/Liquid Waste
9.	Potassium Permanganate	Other RCRA-listed Hazardous Wastes/ Solid or Solidified Waste
10.	Aerosols	Solvents/Liquid Waste
11.	Cylinders	Solvents/Liquid Waste

# Flammable Liquids

1.	Superfund Site Name: Cadie Auto Salvage	
	CERCLIS # <u>ILR000164475</u> State: <u>Illino</u>	ois
2.	Type of Action	
	X Removal	Remedial
	X Fund Financed	Fund Financed
	PRP Financed	PRP Financed
3.	Type and Form of waste; if more than one type, attach see each type:	eparate sheet for this and remaining questions for
	Type: For	m:
	X Solvents	Wastewater
	Dioxins/Furans	X Liquid Waste
	Cyanide	Organic Sludge (greater than 1%
	Heavy Metals (Specify)	Total Solids)
		Inorganic Sludge (less
		than 1% Total
	Acids	Organic Carbon)
	PCBs	Solid or Solidified Waste
	Halogenated Organics	Contaminated Soil and Debris
	Other RCRA-listed Hazardous Wastes (Spe	
	Non-hazardous or de-listed Wastes	
4.	Quantity of Waste: 733	
	Cubic Yards(CY)	Lab Packs
	X Gallons (Gal)	Tons/Lbs
	Drums	
5.	Range, average, and/or representative concentration of the	he contaminants of concern
	Flash Point <140°F	
6.	Pre-treatment of waste before transportation:	
	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
		X None
7.	Receiving RCRA facility name/location/I.D. No./unit(s)	:

	PetroChem Processing Group
	Detroit, Michigan
	MID980615298
	Receiving Region: 5
	Passiving Pagion Offsite Contact (PROC)
•	Receiving Region Offsite Contact (RROC):
	Name: Will Damico Date: 11-23-10
0.	Date of Shipment 11-29-10 Date of Disposal: 12-3-10
1.	Pre-treatment of waste at site before final treatment or disposal:
	Precipitation Neutralization
	Solidification Fixation
	Stabilization Other
	X None
2.	Final method of treatment or disposal/unit receiving:
	Precipitation Neutralization
	Incineration Landfill
	Land Treatment Injection
	X Recovery/Re-Use Other
3.	If waste was landfilled:
	- what disposal cell number or location? Not Applicable
	There a Climan in a still (a pr DVC) Class beneating New April 1.11
	- Type of liner in cell (e.g. PVC, Clay, hypalon) Not Applicable
<del></del>	
4.	Cost of Activities:
	- Cost based on treatment/disposal only: \$ 1,252.05
	- Cost for transportation: \$1,500.00

# RCRA Empty Containers

1.	Superfund Site Name: <u>Cadie Auto Salvage</u>	
	CERCLIS # <u>ILR000164475</u> State: <u>Illinois</u>	<u>S</u>
2.	Type of Action	
	X Removal	Remedial
	X Fund Financed	Fund Financed
	PRP Financed	PRP Financed
3.	Type and Form of waste; if more than one type, attach sep each type:	parate sheet for this and remaining questions for
	Type: Form	
	Solvents	Wastewater
	Dioxins/Furans	Liquid Waste
	Cyanide	Organic Sludge (greater than 1%
	Heavy Metals (Specify)	Total Solids)
		Inorganic Sludge (less
	· · · · · · · · · · · · · · · · · · ·	than 1% Total
	Acids	Organic Carbon)
	PCBs	Solid or Solidified Waste
	Halogenated Organics	X Contaminated Soil and Debris
	Other RCRA-listed Hazardous Wastes (Speci	<del></del>
	X Non-hazardous or de-listed Wastes	
4.	Quantity of Waste: 2.16	
	Cubic Yards(CY)	Lab Packs
	Gallons (Gal)	X Tons
	Drums	<u>—</u>
5,	Range, average, and/or representative concentration of the RCRA Empty Containers 100%	contaminants of concern
<u> </u>		
6.	Pre-treatment of waste before transportation:	
	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
		X None
7.	Receiving RCRA facility name/location/I.D. No./unit(s):  Lee County Landfill	

Not Applicable	
Receiving Region: 5	
Receiving Region Offsite Contact (RROC):	
Name: Will Damico	Date: <u>11-23-10</u>
Date of Shipment 12-1-10	Date of Disposal: <u>12-1-10</u>
Pre-treatment of waste at site before final treatment or d	isposal:
Precipitation	Neutralization
Solidification	Fixation
Stabilization	Other
	X None
Final method of treatment or disposal/unit receiving:	
Precipitation	Neutralization
Incineration	X Landfill
Land Treatment	Injection
Recovery/Re-Use	Other
f waste was landfilled:	
- what disposal cell number or location? 22-23N 25-2	6E 6&8
- Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot o 60 mil HPDE Liner	of compacted clay with a
Cost of Activities:	
· Cost based on treatment/disposal only: \$92.88	
- Cost for transportation: \$750.32	

# <u>Soil</u>

1.	Superfund Site Name: Cadie Auto Salvage		
		State: Illinois	
2.	Type of Action		
	X Removal	Remedial	
	X Fund Financed	Fund Financed	
	PRP Financed	PRP Financed	
3.	Type and Form of waste; if more than one typeach type:	be, attach separate sheet for this and remaining questions for	
	• •	Γ	
	Type:	Form:	
	Solvents	Wastewater	
	Dioxins/Furans	Liquid Waste	
	Cyanide	Organic Sludge (greater than 1%	
	Heavy Metals (Specify)	Total Solids)	
	And the same of th	Inorganic Sludge (less	
	A al da	than 1% Total	
	Acids PCBs	Organic Carbon)	
	— PCBs — Halogenated Organics	Solid or Solidified Waste	
	Other RCRA-listed Hazardous W	X Contaminated Soil and Debris Vastes (Specify)	
	X Non-hazardous or de-listed Wastes		
4.	Quantity of Waste: 15		
	Cubic Yards(CY)	Lab Packs	
	Gallons (Gal)	X Tons	
	Drums	_	
5.	Range, average, and/or representative concentration of the contaminants of concern  Petroleum 1-5%		
***************************************			
6.	Pre-treatment of waste before transportation:		
	Precipitation	Neutralization	
	Solidification	Fixation	
	Stabilization	Other	
		X None	
7.	Receiving RCRA facility name/location/I.D.	No./unit(s):	

	· · · · · · · · · · · · · · · · · · ·	
	Not Applicable	
,		
	Receiving Region: 5	
	Receiving Region Offsite Contact (RROC):	
	Name: Will Damico	Date: <u>11-23-10</u>
	Date of Shipment 12-1-10	Date of Disposal: <u>12-1-10</u>
	Pre-treatment of waste at site before final treatment	atment or disposal:
•	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
		X None
	Final method of treatment or disposal/unit re	
	Precipitation	Neutralization
	Incineration	X Landfill
	Land Treatment	Injection
	Recovery/Re-Use	Other
	If waste was landfilled:	
	- what disposal cell number or location? 22	2-23N 25-26E 6 & 8
		2 201 1 20 20 3 3
_		
	- Type of liner in cell (e.g. PVC, Clay, hypale	on) 3 foot of compacted clay with a
	60 mil HPDE Liner	
	Clark of Anticipies	
	Cost of Activities:	A 57
	- Cost based on treatment/disposal only: \$64	4.37
	- Cost for transportation: \$750.32	·

## Virgin Products and Soil

1.	Superfund Site Name: <u>Cadie Auto Salvage</u>		
	CERCLIS # ILR000164475 State: Illinoi	S	
2.	Type of Action		
	X Removal	Remedial	
	X Fund Financed	Fund Financed	
	PRP Financed	PRP Financed	
3.	Type and Form of waste; if more than one type, attach sep each type:	parate sheet for this and remaining questions for	
	Type: Form	1:	
	Solvents	Wastewater	
	Dioxins/Furans	Liquid Waste	
	Cyanide	Organic Sludge (greater than 1%	
	Heavy Metals (Specify)	Total Solids)	
	xxxxx y xxxxxx (spoxxy)	Inorganic Sludge (less	
		than 1% Total	
	Acids	Organic Carbon)	
	PCBs	Solid or Solidified Waste	
	Halogenated Organics	X Contaminated Soil and Debris	
	Other RCRA-listed Hazardous Wastes (Spec	119)	
	X Non-hazardous or de-listed Wastes		
4.	Quantity of Waste: 6.7		
	Cubic Yards(CY)	Lab Packs	
	Gallons (Gal)	X Tons	
	Drums	<u>A</u> 1003	
	Diums		
5.	Range, average, and/or representative concentration of the contaminants of concern		
	Non-Hazardous Virgin Products 20%		
6.	Pre-treatment of waste before transportation:		
	Precipitation	Neutralization	
	Solidification	Fixation	
	Stabilization	Other	
	NA AND AND AND AND AND AND AND AND AND	X None	
		A A A A A A A A A A A A A A A A A A A	
7.	Receiving RCRA facility name/location/I.D. No./unit(s):		

Receiving Region Offsite Contact (RROC): Name: Will Damico Date: 11-23-10		
Name: Will Damico  Date: 11-23-10  Date of Shipment 12-1-10  Pre-treatment of waste at site before final treatment or disposal:  Precipitation Solidification Neutralization Stabilization Other X None  Final method of treatment or disposal/unit receiving:  Precipitation Neutralization Incineration Neutralization Incineration X Landfill Land Treatment Injection Recovery/Re-Use Other  If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:	Receiving Region: 5	
Date of Shipment 12-1-10  Pre-treatment of waste at site before final treatment or disposal:  Precipitation Neutralization Solidification Tixation Other X None  Final method of treatment or disposal/unit receiving:  Precipitation Neutralization Incineration Neutralization Incineration X Landfill Land Treatment Injection Recovery/Re-Use Other  If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:	Receiving Region Offsite Contact (RROC):	
Pre-treatment of waste at site before final treatment or disposal:  Precipitation Neutralization Solidification Other Stabilization Other X None  Final method of treatment or disposal/unit receiving:  Precipitation Neutralization Incineration X Landfill Land Treatment Injection Recovery/Re-Use Other  If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:	Name: Will Damico	Date: <u>11-23-10</u>
Precipitation Neutralization Solidification Stabilization Other X None Stabilization Other X None Precipitation Neutralization Neutralization Incineration X Landfill Land Treatment Injection Other Other Other Other Other Other Other Other Cost of Activities: Cost of Activities:	Date of Shipment 12-1-10	Date of Disposal: 12-1-10
SolidificationStabilizationOtherX None  Final method of treatment or disposal/unit receiving:  Precipitation Neutralization Neutralization Incineration X Landfill Land Treatment Injection Other  If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:	Pre-treatment of waste at site before final treatment or	disposal:
Stabilization Other X None  Final method of treatment or disposal/unit receiving: Precipitation Neutralization Neutralization Incineration X Landfill Land Treatment Injection Other  If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:	Precipitation	Neutralization
Final method of treatment or disposal/unit receiving:  Precipitation Incineration Incineration Land Treatment Recovery/Re-Use  If waste was landfilled: - what disposal cell number or location?  Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:		Fixation
Final method of treatment or disposal/unit receiving:  Precipitation Incineration Incineration Land Treatment Recovery/Re-Use If waste was landfilled: - what disposal cell number or location?  Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:	Stabilization	Other
Precipitation Neutralization Incineration X_ Landfill Land Treatment Injection Other O		X None
Incineration X_ Landfill Land Treatment Injection Other  If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:	Final method of treatment or disposal/unit receiving:	
Land Treatment Injection Recovery/Re-Use Other  If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:		Neutralization
Recovery/Re-Use Other  If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:		<u> </u>
If waste was landfilled: - what disposal cell number or location? 22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:		_
- what disposal cell number or location?22-23N 25-26E 6 & 8  - Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a60 mil HPDE Liner  Cost of Activities:	Recovery/Re-Use	Other
- Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot of compacted clay with a 60 mil HPDE Liner  Cost of Activities:	If waste was landfilled:	
60 mil HPDE Liner Cost of Activities:	- what disposal cell number or location? 22-23N 25-	-26E 6 <u>&amp;</u> 8
Cost of Activities:	Type of liner in cell (e.g. PVC, Clay, hypalon) 3 foot	of compacted clay with a
	60 mil HPDE Liner	TO THE STATE OF TH
	Cost of Activities	

# <u>Lithium Hydride</u>

1.	Superfund Site Name: Cadie Auto Salvage	
		State: <u>Illinois</u>
2.	Type of Action	
	X Removal	Remedial
	X Fund Financed	Fund Financed
	PRP Financed	PRP Financed
3.	Type and Form of waste; if more than one typeach type:	e, attach separate sheet for this and remaining questions for
	Type:	Form:
	Solvents	Wastewater
	Dioxins/Furans	Liquid Waste
	Cyanide	Organic Sludge (greater than 1%
	Heavy Metals (Specify)	Total Solids)
		Inorganic Sludge (less
		than 1% Total
	Acids	Organic Carbon)
	PCBs	X Solid or Solidified Waste
	Halogenated Organics	Contaminated Soil and Debris
	X Other RCRA-listed Hazardous Wa	
	Reactive	
	Non-hazardous or de-listed Waste	S
4.	Quantity of Waste: 1	
	Cubic Yards(CY)	Lab Packs
	Gallons (Gal)	Tons/Lbs
	XDrums	
5.	Range, average, and/or representative concent	ration of the contaminants of concern
	Lithium Hydride 100%	· · · · · · · · · · · · · · · · · · ·
_		
	<del></del>	
6.	Pre-treatment of waste before transportation:	
	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
		X None
7.	Receiving RCRA facility name/location/I.D. 1	No./unit(s):

	SET Environmental Inc.	
	Houston Toyes	
	TXD055135388	
8.	Receiving Region: 6	
9.	Receiving Region Offsite Contact (RROC):	
<i>7</i> .	Name: Ron Shannon	Date: <u>11-16-10</u>
	110111011110111011101110111	<u> </u>
10.	Date of Shipment 11-30-10	Date of Disposal: 1-5-11
1 1	D	. 1 1
11.	Pre-treatment of waste at site before final treatment	*
	Precipitation Solidification	Neutralization Fixation
	Stabilization	Other
	Statifization	X None
12.	Final method of treatment or disposal/unit receive	
12.	Precipitation	Neutralization
	X Incineration	Landfill
	Land Treatment	Injection
	Recovery/Re-Use	Other
10	101 1011 1-	
13.	If waste was landfilled:	un l'achta
	- what disposal cell number or location? <u>Not A</u>	Applicable
	- Type of liner in cell (e.g. PVC, Clay, hypalon)	Not Applicable
	And a	
	<del></del>	
14.	Cost of Activities:	
,	- Cost based on treatment/disposal only: \$125.00	
	- Cost for transportation: \$112.50	<del></del>
	<u> </u>	

# Ceric Sulfate

1.	Superfund Site Name: <u>Cadie Auto Salvage</u>	
	CERCLIS # <u>ILR000164475</u>	State: Illinois
2.	Type of Action	
2.	X Removal	Remedial
	X Fund Financed	Fund Financed
	PRP Financed	PRP Financed
3.	Type and Form of waster if more than one type	e, attach separate sheet for this and remaining questions for
J.	each type:	e, attach separate sheet for this and remaining questions re
	T.	
	Type:	Form:
	Solvents	Wastewater
	Dioxins/Furans	Liquid Waste
	Cyanide	Organic Sludge (greater than 1%
	Heavy Metals (Specify)	Total Solids)
		Inorganic Sludge (less
		than 1% Total
	Acids	Organic Carbon)
	PCBs	X Solid or Solidified Waste
	Halogenated Organics	Contaminated Soil and Debris
	Other RCRA-listed Hazardous W	astes (Specify)
	XNon-hazardous or de-listed Wastes	
4.	Quantity of Waste: 1	
	Cubic Yards(CY)	Lab Packs
	Gallons (Gal)	Tons/Lbs
	X Drums	**************************************
5.	Range, average, and/or representative concent	ration of the contaminants of concern
٥,	Ceric Sulfate 100%	ration of the contaminants of concern
	<u> </u>	
6	Due treatment of weets hefere transmentation.	
6.	Pre-treatment of waste before transportation:	Novtralization
	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
		X None
7.	Receiving RCRA facility name/location/I.D. 1	No./unit(s):

	Receiving Region: 6	
).	Receiving Region Offsite Contact (RROC):	
•	Name: Ron Shannon	Date: <u>11-16-10</u>
0.	Date of Shipment 11-30-10	Date of Disposal: 1-5-11
11.	Pre-treatment of waste at site before final tre Precipitation Solidification Stabilization	atment or disposal:  Neutralization Fixation Other None
12.	Final method of treatment or disposal/unit re Precipitation Incineration Land Treatment Recovery/Re-Use	<del></del>
13.	If waste was landfilled: - what disposal cell number or location? _N	lot Applicable

- 14.
- Cost of Activities:
   Cost based on treatment/disposal only: \$275.00
   Cost for transportation: \$112.50

# Sodium Hydroxide

1.	Superfund Site Name: Cadie Auto Salvage	**************************************
	CERCLIS # <u>ILR000164475</u>	State: Illinois
2.	Type of Action	
	X Removal	Remedial
	X Fund Financed	Fund Financed
	PRP Financed	PRP Financed
3.	Type and Form of waste; if more than one type each type:	be, attach separate sheet for this and remaining questions for
	Type:	Form:
	Solvents	Wastewater
	Dioxins/Furans	Liquid Waste
	Cyanide	Organic Sludge (greater than 1%
	Heavy Metals (Specify)	Total Solids)
		Inorganic Sludge (less
	<del></del>	than 1% Total
	Acids	Organic Carbon)
	PCBs	X Solid or Solidified Waste
	Halogenated Organics	Contaminated Soil and Debris
	Other RCRA-listed Hazardous W	
	X Non-hazardous or de-listed Waster	S ·
4.	Quantity of Waste: 1	
	Cubic Yards(CY)	Lab Packs
	Gallons (Gal)	Tons/Lbs
	X Drums	
5.	Range, average, and/or representative concen_pH > 12.5_	tration of the contaminants of concern
<del></del>		
6.	Pre-treatment of waste before transportation:	
	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
		X None
7.	Receiving RCRA facility name/location/I.D.	No./unit(s):

Re	eceiving Region: 6	
Re	ceiving Region Offsite Contact (RROC):  Name: Ron Shannon	Date: <u>11-16-10</u>
Da	ate of Shipment 11-30-10	Date of Disposal: 12-14-10
Pr	e-treatment of waste at site before final treatment Precipitation Solidification _X Stabilization	t or disposal:  Neutralization  Fixation  Other  None
Fi	nal method of treatment or disposal/unit receiving Precipitation Incineration Land Treatment Recovery/Re-Use	
	waste was landfilled: vhat disposal cell number or location? Subtitle	Ъ

- Cost based on treatment/disposal only: \$120.00
   Cost for transportation: \$112.50

# <u>Paint</u>

1.	Superfund Site Name: Cadie Auto Salvage		
	CERCLIS # <u>ILR000164475</u> State: J	Illinois	
2.	Type of Action		
	_X_ Removal	Remedial	
	X Fund Financed	Fund Financed	
	PRP Financed	PRP Financed	
3.	Type and Form of waste; if more than one type, atta each type:	ch separate sheet for this and remaining questions	
	Type:	Form:	
	X Solvents	Wastewater	
	Dioxins/Furans	X Liquid Waste	
	Cyanide	Organic Sludge (greater than 1%	
	Heavy Metals (Specify)	Total Solids)	
		Inorganic Sludge (less	
		than 1% Total	
	Acids	Organic Carbon)	
	PCBs	Solid or Solidified Waste	
	Halogenated Organics	Contaminated Soil and Debris	
	Other RCRA-listed Hazardous Wastes	<del></del>	
	Non-hazardous or de-listed Wastes	<u> </u>	
4.	Quantity of Waste: 1		
	Cubic Yards(CY)	Lab Packs	
	Gallons (Gal)	Tons/Lbs	
	<u>X</u> Drums		
5.	Range, average, and/or representative concentration of the contaminants of concern		
	Flash Point <140°F		
6.	Pre-treatment of waste before transportation:		
0.	Precipitation	Neutralization	
	Solidification	Fixation	
	Stabilization	Other	
	Statistical	X None	
		<u> </u>	
7.	Receiving RCRA facility name/location/I.D. No./un	nit(s):	

	Receiving Region: 6	
	220001100000000000000000000000000000000	
	Receiving Region Offsite Contact (RROC):	
	Name: Ron Shannon	Date: <u>11-16-10</u>
).	Date of Shipment 11-30-10	Date of Disposal: 12-21-10
1.	Pre-treatment of waste at site before final trea	atment or disposal:
	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
		X None
2.	Final method of treatment or disposal/unit red	ceiving:
	Precipitation	Neutralization
	Incineration	Landfill
	Land Treatment	Injection
	X Recovery/Re-Use	Other
3.	If waste was landfilled:	
	- what disposal cell number or location? No	ot Applicable

- 14.
- Cost of Activities:
   Cost based on treatment/disposal only: \$275.00
   Cost for transportation: \$112.50

# Potassium Permanganate

1.	Superfund Site Name: <u>Cadie Auto Salvage</u>	
	CERCLIS # ILR000164475 State: Illin	nois
2.	Type of Action	
	X Removal	Remedial
	X Fund Financed	Fund Financed
	PRP Financed	PRP Financed
3.	Type and Form of waste; if more than one type, attach seach type:	separate sheet for this and remaining questions for
	Type: Fo	rm:
	Solvents	Wastewater
	Dioxins/Furans	Liquid Waste
	Cyanide	Organic Sludge (greater than 1%
	Heavy Metals (Specify)	Total Solids)
		Inorganic Sludge (less
		than 1% Total
	Acids	Organic Carbon)
	PCBs	X Solid or Solidified Waste
	Halogenated Organics	Contaminated Soil and Debris
	X Other RCRA-listed Hazardous Wastes (Spe	
	Oxidizer	
	Non-hazardous or de-listed Wastes	
4.	Quantity of Waste: 1	
	Cubic Yards(CY)	Lab Packs
	Gallons (Gal)	Tons/Lbs
	XDrums	
5.	Range, average, and/or representative concentration of	the contaminants of concern
	Potassium Permaganate 100%	
6.	Pre-treatment of waste before transportation:	
	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
		X None
7.	Receiving RCRA facility name/location/I.D. No./unit(s	):
	SET Environmental Inc	

	Houston, Texas	
	TXD055135388	
8.	Receiving Region: 6	
9.	Receiving Region Offsite Contact (RROC):	
<b>,</b>	Name: Ron Shannon	Date: <u>11-16-10</u>
10.	Date of Shipment 11-30-10	Date of Disposal: 1-5-11
11.	Pre-treatment of waste at site before final treatment	t or disposal:
11.	Precipitation	Neutralization
	Solidification	Fixation
	Stabilization	Other
	_	X None
12.	Final method of treatment or disposal/unit receiving	g:
	Precipitation	Neutralization
	X Incineration	Landfill
	Land Treatment	Injection
	Recovery/Re-Use	Other
13.	If waste was landfilled:	
10.	- what disposal cell number or location? Not App	plicable
	animana .	
	- Type of liner in cell (e.g. PVC, Clay, hypalon) No	ot Applicable
	PARTICLE - TOTAL PARTIC	
	<del></del>	

14.

Cost of Activities:

- Cost based on treatment/disposal only: \$450.00 - Cost for transportation: \$112.50

# Aersols

1.	Superfund Site Name: Cadie Auto Salvage	
	CERCLIS # ILR000164475 State: Illinois	S
2.	Type of Action  X Removal  Y Fund Financed PRP Financed	Remedial Fund Financed PRP Financed
3.	Type and Form of waste; if more than one type, attach sep each type:	arate sheet for this and remaining questions for
	Type:         Form           _X Solvents         Dioxins/Furans           Cyanide         Cyanide	Wastewater _X Liquid Waste Organic Sludge (greater than 1%
	— Heavy Metals (Specify)  — Acids — PCBs — Halogenated Organics — Other RCRA-listed Hazardous Wastes (Speci	Total Solids) Inorganic Sludge (less than 1% Total Organic Carbon) Solid or Solidified Waste Contaminated Soil and Debris fy)
4.	Non-hazardous or de-listed Wastes  Quantity of Waste: 1 Cubic Yards(CY) Gallons (Gal)X Drums	Lab Packs Tons/Lbs
5.	Range, average, and/or representative concentration of the  Flash Point <140°F	contaminants of concern
6.	Pre-treatment of waste before transportation:  Precipitation Solidification Stabilization	Neutralization Fixation Other X None
7.	Receiving RCRA facility name/location/I.D. No./unit(s):	

Receiving Region: 6	
Accounting regions o	
Receiving Region Offsite Contact (RROC):	
Name: Ron Shannon	Date: <u>11-16-10</u>
Date of Shipment 11-30-10	Date of Disposal: 12-21-10
Pre-treatment of waste at site before final treat	ment or disposal:
Precipitation	Neutralization
Solidification	Fixation
Stabilization	Other
	X None
Final method of treatment or disposal/unit rece	eiving:
Precipitation	Neutralization
Incineration	Landfill
Land Treatment	Injection
X Recovery/Re-Use	Other
If waste was landfilled:	
- what disposal cell number or location? No	t Applicable

- 14.
- Cost of Activities:
   Cost based on treatment/disposal only: \$290.00
   Cost for transportation: \$112.50

# Cylinders

1.	Superfund Site Name: Cadie Auto Salvage	
	CERCLIS # ILR000164475 State	e: <u>Illinois</u>
2.	Type of Action  X Removal  X Fund Financed PRP Financed	Remedial Fund Financed PRP Financed
3.	Type and Form of waste; if more than one type, a each type:	ttach separate sheet for this and remaining questions for
	Type: X Solvents Dioxins/Furans Cyanide Heavy Metals (Specify)Acids PCBs Halogenated Organics Other RCRA-listed Hazardous Wastes Non-hazardous or de-listed Wastes	Form:  Wastewater X Liquid Waste Organic Sludge (greater than 1%
4.	Quantity of Waste: 245 Cylinders  Cubic Yards(CY)  Gallons (Gal)  Drums	Lab Packs Tons/Lbs
5.	Range, average, and/or representative concentrati  Flash Point <140°F	on of the contaminants of concern
6.	Pre-treatment of waste before transportation:  Precipitation Solidification Stabilization	Neutralization Fixation Other _X None

Receiving RCRA facility name/location/I.D. No./unit(s):

7.

	SET Environmental Inc.		
	Houston, Texas		
	TXD055135388		
	-		
8.	Receiving Region: 6		
9.	Receiving Region Offsite Contact (RROC):		
	Name: Ron Shannon	Date: <u>11-16-10</u>	
10.	Date of Shipment 11-30-10		
	Date of Disposal: See attached sheets		
11.	Pre-treatment of waste at site before final treatment or disposal:		
	Precipitation	Neutralization	
	Solidification	Fixation	
	Stabilization	Other	
		X None	
12.	Final method of treatment or disposal/unit re	<del></del>	
	Precipitation	Neutralization	
	X Incineration	Landfill	
	Land Treatment	Injection	
	Recovery/Re-Use	Other	
13.	If waste was landfilled:		
15,	- what disposal cell number or location? Not Applicable		
		1 227 4 4 11	
	- Type of liner in cell (e.g. PVC, Clay, hypa	Ion) Not Applicable	
		Management of the Control of the Con	
14.	Cost of Activities:	00.500.61	
	- Cost based on treatment/disposal only: \$19	<del>90,700.61</del>	
	- Cost for transportation: \$3,750.00		

844866         005903632JJK 102710CA04         H040         1.0         3/31/2           844867         005903632JJK 102710CA11         H040         5.0         3/31/2           844868         005903632JJK 102710CA14         H040         1.0         3/31/2           844868         005903632JJK 102710CA20         H040         1.0         3/31/2           844871         005903632JJK 102710CA20         H040         1.0         3/31/2           844871         005903632JJK 102910CA01         H040         1.0         3/31/2           844872         005903632JJK 102910CA07         H040         0.3         3/31/2           844873         005903632JJK 102710CA15         H040         2.0         3/31/2           844873         005903632JJK 102710CA15         H040         2.0         3/31/2           844876         005903632JJK 102710CA17         H040         2.0         3/31/2           844876         005903632JJK 102910CA07         H040         2.0         3/31/2           844879         005903632JJK 102910CA06         H040         6.0         3/31/2           844879         005903632JJK 102910CA06         H040         3.0         3/31/2           8448870         005903632JJK 102910CA06	Serial #	Manifest	Cylinder #	Receiving Notes	Mgt Cd	lhs	Disposal
844867         005903632JJK         102710CA11         H040         5.0         3/31/2           844868         005903632JJK         102710CA14         H040         1.0         3/31/2           844869         005903632JJK         102710CA20         H040         1.0         3/31/2           844871         005903632JJK         102910CA03         H040         1.0         3/31/2           844873         005903632JJK         102910CA03         H040         2.0         3/31/2           844874         005903632JJK         102710CA07         H040         2.0         3/31/2           844874         005903632JJK         102710CA07         H040         2.0         3/31/2           844875         005903632JJK         102710CA17         H040         2.0         3/31/2           844876         005903632JJK         102710CA17         H040         2.0         3/31/2           844878         005903632JJK         102910CA07         H040         2.0         3/31/2           844878         005903632JJK         102910CA05         H040         3.0         3/31/2           844879         005903632JJK         102910CA05         H040         3.0         3/31/2           8448810				Trooping Hoto			
644868         005903632_JJK         102710CA12         H040         1.0         3/31/2           844869         005903632_JJK         102710CA20         H040         1.0         3/31/2           844870         005903632_JJK         102710CA20         H040         1.0         3/31/2           844871         005903632_JJK         102910CA03         H040         1.0         3/31/2           844873         005903632_JJK         102910CA03         H040         2.0         3/31/2           844874         005903632_JJK         102710CA07         H040         2.0         3/31/2           844876         005903632_JJK         102710CA17         H040         2.0         3/31/2           844876         005903632_JJK         102710CA17         H040         2.0         3/31/2           844876         005903632_JJK         102910CA07         H040         2.0         3/31/2           844878         005903632_JJK         102910CA05         H040         3.0         3/31/2           844878         005903632_JJK         102710CA05         H040         3.0         3/31/2           844880         005903632_JJK         102710CA06         H040         3.0         3/31/2							
844889         005903832JJK         102710CA14         H040         1.0         3/31/2           844870         005903832JJK         102910CA11         H040         1.0         3/31/2           844871         005903832JJK         102910CA01         H040         1.0         3/31/2           844873         005903832JJK         102910CA07         H040         2.0         3/31/2           844874         005903832JJK         102710CA07         H040         2.0         3/31/2           844875         005903832JJK         102710CA15         H040         2.0         3/31/2           844876         005903832JJK         102910CA07         H040         2.0         3/31/2           844876         005903832JJK         102910CA01         H040         2.0         3/31/2           844877         005903832JJK         102910CA05         H040         6.0         3/31/2           844870         005903832JJK         102710CA05         H040         3.0         3/31/2           844881         005903832JJK         102710CA24         H040         3.0         3/31/2           844881         005903832JJK         102710CA05         H040         3.0         3/31/2           844882<							3/31/2011
844870         005903632JJK         102910CA11         H040         1.0         3/31/2           844871         005903632JJK         102910CA03         H040         3.0         3/31/2           844872         005903632JJK         102910CA07         H040         2.0         3/31/2           844874         005903632JJK         102710CA07         H040         2.0         3/31/2           844875         005903632JJK         102710CA17         H040         2.0         3/31/2           844876         005903632JJK         102910CA07         H040         2.0         3/31/2           844870         005903632JJK         102910CA07         H040         2.0         3/31/2           844870         005903632JJK         102910CA05         H040         6.0         3/31/2           844870         005903632JJK         102710CA08         H040         3.0         3/31/2           844881         005903632JJK         102710CA08         H040         3.0         3/31/2           844882         005903632JJK         102710CA06         H040         3.0         3/31/2           844882         005903632JJK         102710CA05         H040         3.0         3/31/2           8448880							3/31/2011
844871         005903632JJK         102910CA01         H040         1.0         3/31/2           844872         005903632JJK         102910CA07         H040         2.0         3/31/2           844873         005903632JJK         102710CA07         H040         2.0         3/31/2           844876         005903632JJK         102710CA15         H040         2.0         3/31/2           844876         005903632JJK         102910CA07         H040         2.0         3/31/2           844877         005903632JJK         102910CA07         H040         6.0         3/31/2           844878         005903632JJK         102910CA01         H040         6.0         3/31/2           844878         005903632JJK         102910CA05         H040         6.0         3/31/2           844887         005903632JJK         102710CA08         H040         3.0         3/31/2           844881         005903632JJK         102710CA04         H040         3.0         3/31/2           844882         005903632JJK         102710CA05         H040         3.0         3/31/2           844884         005903632JJK         102710CA13         H040         3.0         3/31/2           844888<							3/31/2011
844872 (005903832JJK 102910CA03         H040         3.0 3/31/2           844873 (005903832JJK 102710CA07         H1040         2.0 3/31/2           844874 (005903832JJK 102710CA15         H040         2.0 3/31/2           844875 (005903832JJK 102910CA07         H040         2.0 3/31/2           844878 (005903832JJK 102910CA07         H040         2.0 3/31/2           844878 (005903832JJK 102910CA01         H040         6.0 3/31/2           844878 (005903832JJK 102910CA05         H040         6.0 3/31/2           844879 (005903832JJK 102910CA05         H040         3.0 3/31/2           8448870 (005903832JJK 102710CA08         H040         3.0 3/31/2           844881 (005903832JJK 102710CA04         H040         3.0 3/31/2           844882 (005903832JJK 102710CA05         H040         3.0 3/31/2           844883 (005903832JJK 102710CA05         H040         3.0 3/31/2           844884 (005903832JJK 102710CA05         H040         3.0 3/31/2           844885 (005903832JJK 102710CA05         H040         3.0 3/31/2           844886 (005903832JJK 102710CA13         H040         4.0 3/31/2           844886 (005903832JJK 102710CA13         H040         4.0 3/31/2           844889 (005903832JJK 102710CA09         H040         2.0 3/31/2           844889 (0059038							3/31/2011
844873   005903632JJK   102710CA07   H040   2.0   3/31/2							
844874   005903632JJK   102710CA15   H040   2.0   3/31/2           844875   005903632JJK   102710CA17   H040   2.0   3/31/2           844876   005903632JJK   102910CA07   H040   2.0   3/31/2           844877   005903632JJK   102910CA01   H040   6.0   3/31/2           844878   005903632JJK   102910CA05   H040   6.0   3/31/2           844888   005903632JJK   102710CA08   H040   3.0   3/31/2           844880   005903632JJK   102710CA24   H040   3.0   3/31/2           844881   005903632JJK   102710CA24   H040   3.0   3/31/2           844882   005903632JJK   102710CA05   H040   3.0   3/31/2           844883   005903632JJK   102710CA05   H040   3.0   3/31/2           844884   005903632JJK   102710CA05   H040   3.0   3/31/2           844885   005903632JJK   102710CA13   H040   3.0   3/31/2           844885   005903632JJK   102710CA31   H040   2.0   3/31/2           844887   005903632JJK   102810CA31   H040   2.0   3/31/2           844888   005903632JJK   102910CA09   H040   2.0   3/31/2           844889   005903632JJK   102710CA10   H040   1.0   3/31/2           844889   005903632JJK   102710CA05   H040   1.0   3/31/2           844890   005903632JJK   102710CA09   H040   2.0   3/31/2           844891   005903632JJK   102710CA01   H040   1.0   3/31/2           844892   005903632JJK   102710CA26   H040   1.0   3/31/2           844893   005903632JJK   102710CA26   H040   1.0   3/31/2           844899   005903632JJK   102810CA30   H040   1.0   3/31/2 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>3/31/2011</td>							3/31/2011
844875         005903632JJK         102710CA17         H040         2.0         3/31/2           844876         005903632JJK         102910CA07         H040         6.0         3/31/2           844877         005903632JJK         102910CA05         H040         6.0         3/31/2           844878         005903632JJK         102910CA05         H040         6.0         3/31/2           844880         005903632JJK         102710CA08         H040         3.0         3/31/2           844881         005903632JJK         102710CA24         H040         3.0         3/31/2           844882         005903632JJK         102710CA06         H040         3.0         3/31/2           844883         005903632JJK         102710CA05         H040         3.0         3/31/2           844884         005903632JJK         102710CA13         H040         4.0         3/31/2           844886         005903632JJK         102810CA31         H040         4.0         3/31/2           844887         005903632JJK         10110CA11         H040         2.0         3/31/2           844887         005903632JJK         102710CA19         H040         2.0         3/31/2           844888 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td>3/31/2011</td>						-	3/31/2011
844876         005903632JJK         102910CA07         H040         2.0         3/31/2           844877         005903632JJK         102910CA05         H040         6.0         3/31/2           844879         005903632JJK         102910CA05         H040         6.0         3/31/2           844889         005903632JJK         102710CA08         H040         3.0         3/31/2           844881         005903632JJK         102710CA24         H040         3.0         3/31/2           844882         005903632JJK         102710CA05         H040         3.0         3/31/2           844883         005903632JJK         102710CA05         H040         3.0         3/31/2           844884         005903632JJK         102710CA05         H040         3.0         3/31/2           844885         005903632JJK         102710CA13         H040         3.0         3/31/2           844885         005903632JJK         102710CA13         H040         2.0         3/31/2           844887         005903632JJK         102710CA31         H040         3.0         3/31/2           844888         005903632JJK         102710CA10         H040         2.0         3/31/2           844898<							3/31/2011
844877         005903632JJK         102910CA01         H040         6.0         3/31/2           844878         005903632JJK         102910CA05         H040         6.0         3/31/2           844879         005903632JJK         102710CA08         H040         3.0         3/31/2           844880         005903632JJK         102710CA24         H040         3.0         3/31/2           844881         005903632JJK         102810CA08         H040         3.0         3/31/2           844882         005903632JJK         102710CA05         H040         3.0         3/31/2           844883         005903632JJK         11010CA05         H040         4.0         3/31/2           844884         005903632JJK         102810CA31         H040         4.0         3/31/2           844886         005903632JJK         102810CA31         H040         2.0         3/31/2           844886         005903632JJK         102810CA31         H040         2.0         3/31/2           844888         005903632JJK         102710CA10         H040         2.0         3/31/2           844889         005903632JJK         10110CA57         H040         150.0         3/31/2           844890<		1					3/31/2011
844878         005903632JJK         102910CA05         H040         6.0         3/31/2           844879         005903632JJK         102710CA08         H040         3.0         3/31/2           844880         005903632JJK         102710CA08         H040         3.0         3/31/2           844881         005903632JJK         102710CA05         H040         3.0         3/31/2           844882         005903632JJK         102710CA05         H040         3.0         3/31/2           844884         005903632JJK         102710CA05         H040         3.0         3/31/2           844885         005903632JJK         102710CA13         H040         4.0         3/31/2           844886         005903632JJK         102710CA13         H040         2.0         3/31/2           844886         005903632JJK         102910CA09         H040         2.0         3/31/2           844887         005903632JJK         102910CA09         H040         2.0         3/31/2           844898         005903632JJK         102110CA57         H040         150.0         3/31/2           844890         005903632JJK         102710CA26         H040         2.0         3/31/2           84489							3/31/2011
844879         005903632JJK         102710CA08         H040         3.0         3/31/2           844880         005903632JJK         102810CA08         H040         3.0         3/31/2           844881         005903632JJK         102810CA08         H040         3.0         3/31/2           844882         005903632JJK         110110CA05         H040         3.0         3/31/2           844884         005903632JJK         110110CA05         H040         4.0         3/31/2           844885         005903632JJK         102810CA31         H040         4.0         3/31/2           844886         005903632JJK         110110CA11         H040         3.0         3/31/2           844886         005903632JJK         102710CA09         H040         2.0         3/31/2           844888         005903632JJK         102710CA10         H040         17.0         3/31/2           844890         005903632JJK         110110CA57         H040         15.0         3/31/2           844890         005903632JJK         102710CA26         H040         2.0         3/31/2           844891         005903632JJK         102710CA26         H040         2.0         3/31/2           84489							3/31/2011
844880         005903632JJK         102710CA24         H040         3.0         3/31/2           844881         005903632JJK         102810CA08         H040         3.0         3/31/2           844882         005903632JJK         102710CA05         H040         3.0         3/31/2           844883         005903632JJK         110710CA13         H040         4.0         3/31/2           844884         005903632JJK         102810CA31         H040         4.0         3/31/2           844885         005903632JJK         110110CA11         H040         2.0         3/31/2           844886         005903632JJK         110110CA11         H040         2.0         3/31/2           844889         005903632JJK         102710CA10         H040         17.0         3/31/2           844890         005903632JJK         110110CA57         H040         150.0         3/31/2           844891         005903632JJK         102710CA26         H040         150.0         3/31/2           844892         005903632JJK         102710CA28         H040         1.0         3/31/2           844893         005903632JJK         102710CA30         H040         2.0         3/31/2           84							3/31/2011
844881         005903632JJK         102810CA08         H040         3.0         3/31/2           844882         005903632JJK         102710CA05         H040         3.0         3/31/2           844884         005903632JJK         110110CA05         H040         3.0         3/31/2           844884         005903632JJK         102710CA13         H040         4.0         3/31/2           844886         005903632JJK         102810CA31         H040         2.0         3/31/2           844887         005903632JJK         1102910CA09         H040         2.0         3/31/2           844888         005903632JJK         102710CA10         H040         2.0         3/31/2           844889         005903632JJK         110110CA57         H040         15.0         3/31/2           844891         005903632JJK         102710CA26         H040         2.0         3/31/2           844892         005903632JJK         102710CA26         H040         1.0         3/31/2           844893         005903632JJK         102710CA28         H040         1.0         3/31/2           844893         005903632JJK         102810CA30         H040         2.0         3/31/2           84489				. , , , , , , , , , , , , , , , , , , ,			3/31/2011
844882   005903632JJK   102710CA05   H040   3.0   3/31/2							3/31/2011
844883       005903632JJK       110110CA05       H040       3.0       3/31/2         844884       005903632JJK       102710CA13       H040       4.0       3/31/2         844885       005903632JJK       102810CA31       H040       2.0       3/31/2         844886       005903632JJK       110110CA11       H040       3.0       3/31/2         844887       005903632JJK       102710CA10       H040       17.0       3/31/2         844889       005903632JJK       110110CA57       H040       150.0       3/31/2         844890       005903632JJK       10110CA59       H040       1.0       3/31/2         844891       005903632JJK       102710CA26       H040       1.0       3/31/2         844892       005903632JJK       102710CA28       H040       1.0       3/31/2         844894       005903632JJK       102710CA28       H040       2.0       3/31/2         844895       005903632JJK       102710CA26       H040       3.0       3/31/2         844895       005903632JJK       102810CA01       H040       3.0       3/31/2         844896       005903632JJK       102810CA39       H040       3.0       3/31/2							3/31/2011
844884       005903632JJK       102710CA13       H040       4.0       3/31/2         844885       005903632JJK       102810CA31       H040       2.0       3/31/2         844886       005903632JJK       110110CA11       H040       3.0       3/31/2         844887       005903632JJK       102710CA10       H040       2.0       3/31/2         844889       005903632JJK       102710CA10       H040       17.0       3/31/2         844890       005903632JJK       110110CA57       H040       150.0       3/31/2         844891       005903632JJK       102710CA26       H040       2.0       3/31/2         844892       005903632JJK       102710CA28       H040       1.0       3/31/2         844893       005903632JJK       102710CA30       H040       2.0       3/31/2         844894       005903632JJK       102810CA60       H040       3.0       3/31/2         844895       005903632JJK       102810CA60       H040       3.0       3/31/2         844896       005903632JJK       102810CA01       H040       3.0       3/31/2         844898       005903632JJK       102810CA01       H040       4.0       3/31/2							3/31/2011
844885         005903632JJK         102810CA31         H040         2.0         3/31/2           844886         005903632JJK         110110CA01         H040         3.0         3/31/2           844887         005903632JJK         102910CA09         H040         2.0         3/31/2           844888         005903632JJK         102110CA50         H040         17.0         3/31/2           844889         005903632JJK         110110CA57         H040         150.0         3/31/2           844891         005903632JJK         102710CA26         H040         2.0         3/31/2           844892         005903632JJK         102710CA28         H040         1.0         3/31/2           844893         005903632JJK         102710CA30         H040         2.0         3/31/2           844894         005903632JJK         102810CA60         H040         3.0         3/31/2           844895         005903632JJK         102810CA01         H040         3.0         3/31/2           844896         005903632JJK         110110CA01         H040         4.0         3/31/2           844898         005903633JJK         102810CA35         Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW         H040 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>3/31/2011</td></t<>							3/31/2011
844886         005903632JJK         110110CA11         H040         3.0         3/31/2           844887         005903632JJK         102910CA09         H040         2.0         3/31/2           844888         005903632JJK         102710CA10         H040         17.0         3/31/2           844889         005903632JJK         110110CA57         H040         15.0         3/31/2           844891         005903632JJK         110110CA59         H040         15.0         3/31/2           844892         005903632JJK         102710CA26         H040         2.0         3/31/2           844893         005903632JJK         102710CA28         H040         1.0         3/31/2           844894         005903632JJK         102710CA30         H040         2.0         3/31/2           844895         005903632JJK         102810CA30         H040         3.0         3/31/2           844897         005903632JJK         102810CA31         H040         3.0         3/31/2           844898         005903632JJK         110110CA01         H040         4.0         3/31/2           844899         005903633JJK         102710CA01         H040         4.0         7/13/2           8449							3/31/2011
844887         005903632JJK         102910CA09         H040         2.0         3/31/2           844888         005903632JJK         102710CA10         H040         17.0         3/31/2           844889         005903632JJK         110110CA57         H040         150.0         3/31/2           844891         005903632JJK         110110CA59         H040         150.0         3/31/2           844892         005903632JJK         102710CA26         H040         2.0         3/31/2           844893         005903632JJK         102710CA30         H040         2.0         3/31/2           844894         005903632JJK         102810CA60         H040         3.0         3/31/2           844895         005903632JJK         102810CA01         H040         3.0         3/31/2           844897         005903632JJK         102810CA39         H040         3.0         3/31/2           844898         005903632JJK         110110CA01         H040         4.0         3/31/2           844899         005903633JJK         102710CA01         H040         4.0         7/13/2           844900         005903633JJK         102910CA35         Isoprene, drilled by DF, FTIR analysis 8/10/11 - SW         H040         <							3/31/2011
844888         005903632JJK         102710CA10         H040         17.0         3/31/2           844889         005903632JJK         110110CA57         H040         150.0         3/31/2           844890         005903632JJK         110110CA59         H040         150.0         3/31/2           844891         005903632JJK         102710CA26         H040         2.0         3/31/2           844892         005903632JJK         102710CA28         H040         1.0         3/31/2           844893         005903632JJK         102710CA30         H040         2.0         3/31/2           844894         005903632JJK         102810CA01         H040         3.0         3/31/2           844895         005903632JJK         102810CA39         H040         3.0         3/31/2           844897         005903632JJK         110110CA01         H040         4.0         3/31/2           844898         005903633JJK         102710CA01         H040         4.0         7/13/2           844900         005903633JJK         102810CA35         Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW         H040         4.0         7/13/2           844901         005903633JJK         102910CA28         Molybdenum Hexaflu							3/31/2011
844889       005903632JJK       110110CA57       H040       150.0       3/31/2         844890       005903632JJK       110110CA59       H040       150.0       3/31/2         844891       005903632JJK       102710CA26       H040       2.0       3/31/2         844892       005903632JJK       102710CA30       H040       2.0       3/31/2         844893       005903632JJK       102810CA60       H040       3.0       3/31/2         844895       005903632JJK       102810CA01       H040       3.0       3/31/2         844897       005903632JJK       110110CA01       H040       3.0       3/31/2         844898       005903632JJK       110110CA01       H040       4.0       3/31/2         844899       005903633JJK       110110CA01       H040       4.0       3/31/2         844890       005903633JJK       102710CA01       H040       4.0       7/13/2         844901       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844902       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       4.0       8/16/2         844903       005903633JJK							
844890       005903632JJK       110110CA59       H040       150.0       3/31/2         844891       005903632JJK       102710CA26       H040       2.0       3/31/2         844892       005903632JJK       102710CA30       H040       1.0       3/31/2         844894       005903632JJK       102810CA60       H040       32.0       3/31/2         844895       005903632JJK       102810CA01       H040       3.0       3/31/2         844897       005903632JJK       102810CA39       H040       4.0       3/31/2         844898       005903632JJK       110110CA01       H040       4.0       3/31/2         844899       005903633JJK       102710CA01       H040       4.0       7/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       2.0       8/16/2         844902       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0					H040		
844891       005903632JJK       102710CA26       H040       2.0       3/31/2         844892       005903632JJK       102710CA30       H040       2.0       3/31/2         844894       005903632JJK       102810CA60       H040       32.0       3/31/2         844895       005903632JJK       102810CA01       H040       3.0       3/31/2         844897       005903632JJK       1102810CA39       H040       4.0       3/31/2         844898       005903632JJK       110110CA01       H040       4.0       3/31/2         844899       005903633JJK       102710CA01       H040       4.0       7/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       2.0       8/16/2         844903       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride, ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0					H040		3/31/2011
844892       005903632JJK       102710CA28       H040       1.0       3/31/2         844893       005903632JJK       102810CA60       H040       2.0       3/31/2         844894       005903632JJK       102810CA01       H040       3.0       3/31/2         844896       005903632JJK       102810CA39       H040       3.0       3/31/2         844897       005903632JJK       110110CA01       H040       4.0       3/31/2         844898       005903633JJK       102710CA01       H039       2.0       9/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       2.0       8/16/2         844902       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0					H040		3/31/2011
844893       005903632JJK       102710CA30       H040       2.0       3/31/2         844894       005903632JJK       102810CA60       H040       32.0       3/31/2         844895       005903632JJK       102810CA39       H040       3.0       3/31/2         844897       005903632JJK       110110CA01       H040       4.0       3/31/2         844898       005903632JJK       110110CA12       H039       2.0       9/13/2         844899       005903633JJK       102710CA01       H040       4.0       7/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       6.0       8/12/2         844902       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR							3/31/2011
844894       005903632JJK       102810CA60       H040       32.0       3/31/2         844895       005903632JJK       102810CA39       H040       3.0       3/31/2         844896       005903632JJK       110110CA01       H040       4.0       3/31/2         844898       005903632JJK       110110CA12       H039       2.0       9/13/2         844899       005903633JJK       102710CA01       H040       4.0       7/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       6.0       8/12/2         844902       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0	844893	005903632JJK	102710CA30				3/31/2011
844895       005903632JJK       102810CA01       H040       3.0       3/31/2         844896       005903632JJK       110110CA01       H040       4.0       3/31/2         844897       005903632JJK       110110CA01       H039       2.0       9/13/2         844899       005903633JJK       102710CA01       H040       4.0       7/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       6.0       8/12/2         844902       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0	844894	005903632JJK	102810CA60				3/31/2011
844897       005903632JJK       110110CA01       H040       4.0       3/31/2         844898       005903632JJK       110110CA12       H039       2.0       9/13/2         844899       005903633JJK       102710CA01       H040       4.0       7/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       6.0       8/12/2         844902       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0							3/31/2011
844898       005903633JJK       110110CA12       H039       2.0       9/13/2         844899       005903633JJK       102710CA01       H040       4.0       7/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       6.0       8/12/2         844902       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0							3/31/2011
844899       005903633JJK       102710CA01       H040       4.0       7/13/2         844900       005903633JJK       102810CA35       Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW       H061       5.0         844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       6.0       8/12/2         844902       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0							3/31/2011
844900 005903633JJK 102810CA35 Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW H061 5.0 10/19/2 844901 005903633JJK 102910CA17 Methyl Chloride, FTIR analysis 8/10/11 - SW H040 6.0 8/12/2 844902 005903633JJK 110110CA20 H040 2.0 8/16/2 844903 005903633JJK 102910CA28 Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR							
844901 005903633JJK 102910CA17 Methyl Chloride, FTIR analysis 8/10/11 - SW H040 6.0 8/12/2 844902 005903633JJK 110110CA20 H040 2.0 8/16/2 844903 005903633JJK 102910CA28 Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR							7/13/2011
844901       005903633JJK       102910CA17       Methyl Chloride, FTIR analysis 8/10/11 - SW       H040       6.0       8/12/2         844902       005903633JJK       110110CA20       H040       2.0       8/16/2         844903       005903633JJK       102910CA28       Molybdenum Hexafluoride , ID by NIST Peak Data (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR       H111       14.0	844900	005903633JJK	102810CA35	Isoprene, drilled by DF, FTIR analysis 10/19/11 - SW	H061	5.0	
844902 005903633JJK 110110CA20					<u> </u>	<u> </u>	10/19/2011
844903 005903633JJK 102910CA28 Molybdenum Hexafluoride , ID by NIST Peak Data H111 14.0 (741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR				Methyl Chloride, FTIR analysis 8/10/11 - SW			
(741 cm-1), dark blue/ violet residual left on fittings after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR	844902	005903633JJK	110110CA20				
after sampling, cyl @ 2" Hg psig @ 30C, pH=0, FTIR	844903	005903633JJK	102910CA28		H111	14.0	
1							- 40 - 50
				analysis 8/22/11 - SW	<u> </u>		9/26/2011
							3/31/2011
						<del></del>	3/31/2011
			<u> </u>	10/19/11 - SW			10/20/2011
	844907	005903633JJK	102910CA41	Methanethiol, FTIR analysis 7/27/11 - SW		3.0	
844908 005903633JJK 102710CA19 H040 3.0 3/31/2	844908	005903633JJK	102710CA19		H040	<del></del>	
844909 005903633JJK 110110CA03 Bad Valve - Cylinder is plugged. No valve present. H061 13.0 8/17/11 - SW	844909	005903633JJK	110110CA03		H061	13.0	
Acetone, drilled by DF, FTIR/ATR analysis of vapor					1		ALCO AND
							10/20/2011

844911       005903633JJK       102810CA57       H121         844912       005903633JJK       102810CA59       Trifluorosilane/ trichlorosilane mix, FTIR analysis       H040         844913       005903633JJK       102810CA21       H121       4         844914       005903633JJK       102810CA22       H121       4         844915       005903633JJK       102810CA23       H121       4         844916       005903633JJK       102810CA24       H121       4         844917       005903633JJK       110110CA28       H121       4         844918       005903633JJK       110110CA31       H121       3         844920       005903633JJK       110110CA37       H121       3         844921       005903633JJK       102710CA22       H121       3         844922       005903633JJK       102710CA21       H121       4         844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA79       H121       4         844926       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H	2.0 6.0 4.0 4.0 4.0 4.0 3.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0	10/11/2011 10/11/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 10/21/2011
844911       005903633JJK       102810CA57       H121         844912       005903633JJK       102810CA59       Trifluorosilane/ trichlorosilane mix, FTIR analysis       H040         844913       005903633JJK       102810CA21       H121       4         844914       005903633JJK       102810CA22       H121       4         844915       005903633JJK       102810CA23       H121       4         844916       005903633JJK       102810CA24       H121       4         844917       005903633JJK       110110CA28       H121       4         844918       005903633JJK       110110CA31       H121       4         844920       005903633JJK       110110CA37       H121       3         844921       005903633JJK       102710CA22       H121       3         844922       005903633JJK       102710CA21       H121       4         844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       H121       4         844926       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H	4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0	10/11/2011 10/11/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 10/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844912	4.0 4.0 4.0 4.0 4.0 3.0 4.0 4.0 4.0 5.0 4.0	10/11/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
8/3/11 - SW   8/3/11 - SW   844913   005903633JJK   102810CA21   H121   4844914   005903633JJK   102810CA22   H121   4844915   005903633JJK   102810CA23   H121   4844916   005903633JJK   102810CA24   H121   4844917   005903633JJK   10110CA28   H121   4844919   005903633JJK   10110CA31   H121   4844919   005903633JJK   10110CA37   H121   4844919   005903633JJK   10110CA37   H121   4844920   005903633JJK   102710CA32   H121   3844921   005903633JJK   102710CA31   H121   4844922   005903633JJK   102710CA31   H121   4844923   005903633JJK   102710CA31   H121   4844924   005903633JJK   102810CA27   H121   4844924   005903633JJK   10110CA79   H121   4844925   005903633JJK   102710CA31   Boron Trichloride, drilled by DF, FTIR analysis   H111   4844926   005903633JJK   102710CA18   Boron Trichloride, drilled by DF, FTIR analysis   H111   4844926   005903633JJK   102710CA18   Boron Trichloride, drilled by DF, FTIR analysis   H111   4844926   005903633JJK   102710CA18   Boron Trichloride, drilled by DF, FTIR analysis   H111   4844926   005903633JJK   102710CA44   Suspected Molbdenum Hexafluoride, Silicon   Tetrafluoride/ HF peaks detected, No strong MoF6 ( as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis   7/26/11 - SW	4.0 4.0 4.0 4.0 4.0 3.0 4.0 4.0 4.0 5.0 4.0	7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844913       005903633JJK       102810CA21       H121       4         844914       005903633JJK       102810CA22       H121       4         844915       005903633JJK       102810CA24       H121       4         844916       005903633JJK       110110CA28       H121       4         844917       005903633JJK       110110CA31       H121       4         844918       005903633JJK       110110CA37       H121       3         844920       005903633JJK       110110CA33       H111       4         844921       005903633JJK       102710CA22       H121       3         844922       005903633JJK       102710CA31       H121       4         844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       Boron Trichloride, drilled by DF, FTIR analysis       H111       4         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2	4.0 4.0 4.0 4.0 3.0 4.0 4.0 4.0 4.0 4.0 4.0	7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844914       005903633JJK       102810CA22       H121       4         844915       005903633JJK       102810CA23       H121       4         844916       005903633JJK       102810CA24       H121       4         844917       005903633JJK       110110CA28       H121       4         844918       005903633JJK       110110CA31       H121       4         844919       005903633JJK       110110CA37       H121       3         844920       005903633JJK       102710CA22       H121       3         844921       005903633JJK       102710CA31       H121       4         844922       005903633JJK       102810CA27       H121       4         844924       005903633JJK       102810CA27       H121       4         844925       005903633JJK       110110CA79       H121       4         844926       005903633JJK       102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111       5         844927       005903633JJK       102710CA14       Suspected Molbdenum Hexafluoride, Silicon       H121       4         844927       005903633JJK       102710CA14       Suspected Molbdenum Hexafluoride, Silicon       H121       2	4.0 4.0 4.0 4.0 3.0 4.0 4.0 4.0 4.0 4.0 4.0	7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 10/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844915       005903633JJK       102810CA23       H121       4         844916       005903633JJK       102810CA24       H121       4         844917       005903633JJK       110110CA28       H121       4         844918       005903633JJK       110110CA31       H121       4         844920       005903633JJK       110110CA37       H121       3         844921       005903633JJK       102710CA22       H121       3         844922       005903633JJK       102710CA31       H121       4         844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       H111       5         844926       005903633JJK       102710CA48       Boron Trichloride, drilled by DF, FTIR analysis       H111       4         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon	4.0 4.0 4.0 3.0 4.0 4.0 4.0 4.0 4.0	7/21/2011 7/21/2011 7/21/2011 7/21/2011 7/21/2011 10/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844916       005903633JJK       102810CA24       H121         844917       005903633JJK       110110CA28       H121         844918       005903633JJK       110110CA31       H121         844919       005903633JJK       110110CA37       H121         844920       005903633JJK       102710CA22       H121         844921       005903633JJK       102710CA31       H121         844923       005903633JJK       102810CA27       H121         844924       005903633JJK       110110CA79       H121         844925       005903633JJK       110110CA76       H111         844926       005903633JJK       102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121         844928       005903633JJK       102710CA44       H121       A12	4.0 4.0 3.0 4.0 3.0 4.0 4.0 5.0	7/21/2011 7/21/2011 7/21/2011 7/21/2011 10/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844917       005903633JJK       110110CA28       H121       4         844918       005903633JJK       110110CA37       H121       4         844919       005903633JJK       110110CA37       H121       3         844920       005903633JJK       102710CA22       H121       3         844921       005903633JJK       102710CA31       H121       4         844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       H111       5         844926       005903633JJK       1102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111       5         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844928<	4.0 3.0 4.0 4.0 4.0 4.0 5.0	7/21/2011 7/21/2011 7/21/2011 10/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844918       005903633JJK       110110CA31       H121       4         844919       005903633JJK       110110CA37       H121       3         844920       005903633JJK       102710CA22       H121       3         844921       005903633JJK       102710CA31       H121       4         844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       H111       5         844926       005903633JJK       102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111       4         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       2         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121 <td>4.0 3.0 4.0 4.0 4.0 4.0 5.0</td> <td>7/21/2011 7/21/2011 10/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011</td>	4.0 3.0 4.0 4.0 4.0 4.0 5.0	7/21/2011 7/21/2011 10/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844919       005903633JJK       110110CA37       H121       3         844920       005903633JJK       110110CA33       H111       4         844921       005903633JJK       102710CA22       H121       3         844922       005903633JJK       102710CA31       H121       4         844924       005903633JJK       102810CA27       H121       4         844925       005903633JJK       110110CA76       H111       5         844926       005903633JJK       102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111       4         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       7         Tetrafluoride/ HF peaks detected, No strong MoF6 (as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnact. Blue residual left on valve surface, FTIR analysis       Blue residual left on valve surface, FTIR analysis	3.0 4.0 4.0 4.0 4.0 5.0	7/21/2011 10/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844920       005903633JJK       110110CA33       H111       4         844921       005903633JJK       102710CA22       H121       3         844922       005903633JJK       102710CA31       H121       4         844924       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       H111       5         844926       005903633JJK       102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111       4         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       7         Tetrafluoride/ HF peaks detected, No strong MoF6 (as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data.Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW       H121       A	4.0 4.0 4.0 4.0 5.0 4.0	10/21/2011 7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844921       005903633JJK       102710CA22       H121       3         844922       005903633JJK       102710CA31       H121       4         844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       H111       5         844926       005903633JJK       102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111       4         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon Tetrafluoride/ HF peaks detected, No strong MoF6 ( as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW	3.0 4.0 4.0 4.0 5.0 4.0	7/21/2011 7/21/2011 7/21/2011 21-Jul 9/28/2011
844922       005903633JJK       102710CA31       H121       4         844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       H111       5         844926       005903633JJK       102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111       4         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon       H121       4         Tetrafluoride/ HF peaks detected, No strong MoF6 (as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW	4.0 4.0 4.0 5.0 4.0	7/21/2011 7/21/2011 21-Jul 9/28/2011
844923       005903633JJK       102810CA27       H121       4         844924       005903633JJK       110110CA79       H121       4         844925       005903633JJK       110110CA76       H111       5         844926       005903633JJK       102710CA18       Boron Trichloride, drilled by DF, FTIR analysis       H111       4         844927       005903633JJK       102710CA44       Suspected Molbdenum Hexafluoride, Silicon Tetrafluoride/ HF peaks detected, No strong MoF6 (as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW	4.0 4.0 5.0 4.0	7/21/2011 21-Jul 9/28/2011
844924 005903633JJK 110110CA79 H121 4 844925 005903633JJK 110110CA76 H111 5 844926 005903633JJK 102710CA18 Boron Trichloride, drilled by DF, FTIR analysis H111 10/20/11 - SW  844927 005903633JJK 102710CA44 Suspected Molbdenum Hexafluoride, Silicon Tetrafluoride/ HF peaks detected, No strong MoF6 (as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW	4.0 5.0 4.0	21-Jul 9/28/2011
844925 005903633JJK 110110CA76	5.0 4.0	9/28/2011
844926 005903633JJK 102710CA18 Boron Trichloride, drilled by DF, FTIR analysis 10/20/11 - SW  844927 005903633JJK 102710CA44 Suspected Molbdenum Hexafluoride, Silicon Tetrafluoride/ HF peaks detected, No strong MoF6 ( as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW	1.0	
844927 005903633JJK 102710CA44 Suspected Molbdenum Hexafluoride, Silicon Tetrafluoride/ HF peaks detected, No strong MoF6 ( as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data.Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW		10/20/2011
844927 005903633JJK 102710CA44 Suspected Molbdenum Hexafluoride, Silicon Tetrafluoride/ HF peaks detected, No strong MoF6 ( as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW	2.0	
Tetrafluoride/ HF peaks detected, No strong MoF6 ( as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data.Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW		
as profiled) peaks detected in the 741Cm-1 area as predicted by NIST data. Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW		
predicted by NIST data.Slight fuming on disconnnect. Blue residual left on valve surface, FTIR analysis 7/26/11 - SW		
Blue residual left on valve surface, FTIR analysis 7/26/11 - SW	١	
7/26/11 - SW		
	- 1	9/27/2011
10448Z0 10008U0000JJN 110Z0 (UCAOU (	1.0	9/27/2011
	3.0	2/9/2011
	3.0	
	3.0	
	3.0	8/29/2011
844933 005903633JJK 102910CA02 Bad Valve - Frozen Plug 8/9/11 - SW H121		11/3/2011
	5.0	2/9/2011
	5.0	
analysis 7/27/11 - SW	- 1	7/27/2011
844936 005903633JJK 102810CA37 H121	5.0	2/9/2011
844937 005903633JJK 102710CA04 H121		10/18/2011
844938   005903633JJK   102710CA32   Boron Trichloride, FTIR analysis 8/8/11 - SW   H121   3	3.0	9/27/2011
	3.0	9/27/2011
844940   005903633JJK   102710CA50   Chloropentafluoroethane (R-115), FTIR analysis   H040	1.0	
7/26/11 - SW		7/26/2011
844941 005903633JJK 102910CA16 Chloropicrin, methyl bromide mix (with CO2, CO, NO   H040   3	3.0	
and H20 contaminates or decomposition products),	-	
FTIR analysis 7/27/11 - SW		8/17/2011
844942 005903633JJK 102910CA21 Chloropicrin/Methyl Bromide mix , FTIR analysis H040	4.0	
8/2/11 - SW		8/17/2011
844943 005903633JJK 102910CA31 Isopropyl sulfide ( VP 18.6 mmHg @ 25C), FTIR H040 10	0.0	
analysis 8/17/11 - SW		8/26/2011
	2.0	
analysis 7/26/11 - SW		7/26/2011
	4.0	
8/2/11 - SW		8/2/2011

,

		Cylinder #	Receiving Notes	Mgt Cd	lbs	Disposal	
844946	005903633JJK	110110CA27	Empty, no pressure or liquid, valve open to atm, 8/2/11 - SW	H039	4.0	8/2/2011	
844947	005903633JJK	110110CA68	Bad valve - Frozen Stem 8/2/11 - SW	H141	0.0	10/18/2011	
	005903633JJK		Unable to detect contents with FTIR, B 580 CGA CG 4, 800 psig, FTIR analysis 8/17/11 - SW	H111	11.0	9/26/2011	
			Empty, no liquid or pressure, 8/8/11 - SW	H039	4.0	8/16/2011	
844950	005903633JJK	102910CA12	Trifluoroacetyl fluoride, FTIR analysis 8/8/11 - SW	H040	3.0	9/13/2011	
844951	005903633JJK	102810CA26		H111	4.0	9/26/2011	
844952	005903633JJK		Chlorotrifluoromethane (R-13), FTIR analysis 8/18/11 - SW	W		9/8/2011	
844953	005903633JJK	102810CA32	32 Hexafluoroacetone, confirmed by FTIR analysis 8/3/11 H040 - SW		2.0	8/12/2011	
844954	005903633JJK	102810CA51	Hexafluoroacetone, Confirmed by FTIR analysis 8/3/11 - SW	H040	2.0	8/16/2011	
844955	005903633JJK	102910CA24		H039	23.0		
844956	005903633JJK	102710CA36		H121		1/27/2011	
844957	005903633JJK	110110CA02		H121		1/27/2011	
844958	005903633JJK	110110CA10		H071	3.0	1/27/2011	
	005903633JJK		Bad Valve, Damaged CGA threads, 8/11/11 - SW	H039		10/18/2011	
	005903633JJK		Bad valve - Frozen Stem, 8/2/11 - SW	H121		10/18/2011	
	005903633JJK				2.0	5/25/2011	
	005903633JJK						
	005903633JJK			H121	3.0 6/22/2011		
	005903633JJK			H121	3.0		
844965	005903633JJK				4.0	9/27/2011	
844966	005903633JJK	102910CA18	18 Chloromethane / Acetone mix ( Parathion not detected), FTIR analysis 7/27/11 - SW		3.0	9/13/2011	
844967	005903633JJK	110110CA13	13 SUSPECT Organometallic, Ethane / ethylene H040 detected, liquid, cyl fumes when exposed to air, slight metallic odor, white residuals deposited on fittings (Basic pH), FTIR analysis 8/3/11 - SW		3.0	9/20/2011	
844968	005903633JJK	102710CA33		H141	3.0	11/9/2011	
844969	005903633JJK	102810CA15	Empty, no liquid or pressure, Bronze CGA660 CG-2, N2 added to get sample, FTIR analysis 8/8/11- SW	H039	3.0	3.0	
844970	005903633JJK	102810CA28	Phosphorus pentafluoride, FTIR analysis 8/2/11 - SW	H121	3.0	8/11/2011 0 9/27/2011	
844971	005903633JJK	110110CA38	Bad Valve - Blocked Port Ethane detected, drilled by DF, reports liquid in cylinder, that plus relatively low abs indicates an possible organometallic material ( ie. triethyl aluminum), ATR scans of solids created were of little	H141	3.0		
844972	005903633JJK	102810CA52	help.FTIR analysis 10/19/11 - SW Methyl Disulfide( residual low abs peaks), FTIR	H040	4.0	10/19/2011	
			analysis 7/27/11 - SW			8/26/2011	
	005903633JJK		Bad Valve - Excessive Corrosion 08/16/11 - SW	H141	0.0	10/19/2011	
844974	005903633JJK	102710CA21	Sent to Bijan for analysis WO:67387 BOL:081511- 8/15/11- SW	H141	3.0	11/10/2011	
844975	005903633JJK	102810CA17	Bad Valve - Blocked Port, 8/16/11 - SW	H141	5,0	10/18/2011	

Serial #	Manifest	Cylinder #	Receiving Notes	Mgt Cd	lbs	Disposal
	005903633JJK		Empty, trace Dichlorodifluoromethane (R-12)	H040	1.0	
			detected, (insecticides not detected by FTIR although cylinder type is commonly used for Pyrethrin/ R12			
:			mixes), FTIR analysis 7/26/11 - SW			
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			7/26/2011
	005903633JJK			H040	1,0	12/7/2011
844978	005903633JJK	102910CA20	Bad Valve - Blocked Port	H061	7.0	
			Chloromethane, drilled by DF, FTIR analysis 10/20/11 -	<b> </b>		
			SW		4.4	10/20/2011
	005903633JJK			H121	4.0	
	005903633JJK	·		H121 4		
	005903633JJK			H121	4.0	
L	005903633JJK		The Manhaman day to the second	H040	4.0	
	005903633JJK			H039	18.0	
	005903633JJK		Water the state of	H039	80.0	5/20/2011
844985	005903633JJK	102910CA30	Boron Trichloride, approx 20psig @ 35 C, white wisps	H111	15.0	
			during purge, ASB CGA660 CG 2 or 3, FTIR analysis			
			8/17/11 - SW			9/26/2011
			1,3-Butadiene, FTIR analysis 7/27/11 - SW	H061	3.0	9/12/2011
	005903633JJK			H121	122.0	
<u> </u>	005903633JJK			H121	122.0	5/25/2011
	005903633JJK			H039	122.0	
	005903633JJK			H039	122.0	
844991	005903633JJK	110110CA61	Chlorine, yellow green color VP over 120 psig @ 35C, +OX, ASB 660 CG-2 or 3, FTIR analysis 8/22/11- SW	H111	122.0	
						9/27/2011
844992	005903633JJK	110110CA62		H071	123.0	3/24/2011
	005903633JJK		1-Pentyne, FTIR analysis 8/8/11 - SW	H061	3.0	
	005903633JJK		Bad Valve, Chlorine, +OX, pH=0, Cl2 odor, 8/11/11 -	H111	3.0	
			sw			9/26/2011
	005903633JJK			H111_	3.0	10/12/2011
	005903633JJK			H121	3.0	
844997	005903633JJK	110110CA69		H121	3.0	
	005903633JJK			H121	3.0	
	005903633JJK	<del>1 </del>		H121	3.0	6/22/2011
	005903633JJK			H111	3.0	
845001	005903633JJK	110110CA51		H111	17.0	
	005903633JJK			H111	14.0	
	005903633JJK		·	H111	5.0	11/3/2011
845004	005903633JJK	110110CA22	3,3,3-Trifluoro-1-propyne, FTIR analysis 8/8/11 - SW	H040	4.0	8/16/2011
845005	005903633JJK	102810CA41	Bad Valve - blocked valve ports, 8/11/11 - SW	H111	8.0	OF TATE OF T
1			Silicon Tetrachloride, drilled by DF, FTIR analysis	,,,,,		
			10/18/11 - SW			10/18/2011
845006	005903633JJK	102910CA26	Tetrafluoroethylene; CFC-1114, FTIR analysis 8/18/11	H061	9.0	
			- SW			9/1/2011
845007	005903633JJK	102810CA38	Tetrafluoroethylene; CFC-1114, FTIR analysis 8/16/11	H061	4.0	<del></del>
			- SW			8/17/2011
845008	005903633JJK	102810CA42	Empty, no pressure, liquid pH=6 rusty color, very	H039	4.0	
-			small methane signature, valve on one end was open			
			to to atm, FTIR analysis 7/28/11 - SW			8/1/2011

Serial #	Manifest	Cylinder #			Disposal		
845009	005903633JJK	110110CA40	Bad Valve Hydrogen Selenide, FTIR analysis 7/27/11 -	H040	3.0		
			SW			8/26/2011	
845010	005903633JJK	102910CA36	Bad Valve - Frozen Dust Plug, 8/9/11 - SW	H111	3.0		
			Chlorine Trifluoride, drilled by DF, FTIR analysis			14,0,00044	
0.45044	0050000001446	1007100151	11/02/11 - SW	11444	4.0	11/3/2011	
	005903633JJK		Bad Valve - Blocked Port, 8/16/11 - SW	H141	4.0		
			Perchloryl fluoride, FTIR analysis 8/11/11 - SW	H111	4.0		
			Dichlorodifluoromethane; CFC-12, FTIR analysis 7/26/11 - SW	H040	3.0	7/27/2011	
			Empty, no liquid or pressure, last contained R12, FTIR analysis 7/26/11 - SW	H039	3.0	7/27/2011	
845015	005903633JJK	102710CA52	Chloropicrin; Nitrotrichloromethane, FTIR analysis 8/3/11 - SW	H040	3.0	8/17/2011	
845016	005903633JJK	102710CA54	Chloropicrin, FTIR analysis 7/27/11 - SW	H040	3.0	<del></del>	
			Dichlorodifluoromethane; CFC-12, FTIR analysis 8/2/11 - SW	H040	3.0	8/2/2011	
845018	005903633JJK	102710CA56	Chloropicrin, FTIR analysis 8/2/11 - SW	H040	3.0		
845019	005903633JJK	102710CA57	Chloropicrin, FTIR analysis 7/27/11 - SW	H040	3.0		
845020	005903633JJK	102710CA58	Empty, no liquid or pressure, last contained R12, FTIR analysis 8/2/11 - SW	H039	3,0	8/1/2011	
845021	005903633JJK	102710CA60	Chloropicrin, FTIR analysis 8/4/11 - SW	H040	3,0	8/17/2011	
845022	005903633JJK	102710CA61	Empty, no liquid or pressure, last contained R12, FTIR analysis 8/02/11- SW	H039	3.0	3.0 8/1/2011	
845023	005903633JJK	102810CA02	Dichlorodifluoromethane; CFC-12, FTIR analysis 7/27/11 - SW	H040	3.0	3.0 7/27/2011	
845024	005903633JJK	102810CA06	Empty, no pressure, water inside cylinder, FTIR analysis 8/3/11 - SW	H039			
845025	005903633JJK	102810CA11	Bad Valve - Blocked Port 8/2/11 - SW	H111	4.0	4.0	
			Sulfur Dioxide, drilled by DF, FTIR analysis 10/18/11 - SW			10/18/2011	
845026	005903633JJK	102810CA13	Isobutene/1,3-Butadiene mix, FTIR analysis 8/2/11 -	H061	3.0		
845027	005903633JJK	102810CA20	Empty, no liquid or pressure, trace ethane detected, N2 added to get sample, FTIR analysis 8/3/11 - SW	H039	3.0 8/12/2011		
845028	005903633JJK	102810CA29	Empty, No liquid or pressure, FTIR analysis 7/26/11 - SW	H039	1.0		
845029	005903633JJK	102810CA33	Sent to Bijan for analysis WO:67387 BOL:081511- 8/15/11- SW Chlorine trifluoride, drilled by DF, FTIR analysis	H111			
			11/1/11 - SW			11/1/2011	
845030	005903633JJK	102810CA49	Empty, no liquid or pressure, FTIR analysis 7/28/11 - SW	H039	4.0		
845031	005903633JJK	102810CA56	Sent to Bijan for analysis WO:67387 BOL:081511-8/15/11-SW	H111 3.0			
			1,2,2,2,Tetrafluoroethanesulfonylfluoride, drilled by			14/4/0044	
045020	006003633144	1020100 409	DF, FTIR analysis 11/1/11 - SW Empty, no liquid or pressure, FTIR analysis 8/2/11 -	H039	4.0	11/1/2011	
845032	005903633JJK	102810CA08	SW	11008	4.0	8/2/2011	
845033	005903633JJK	1029100432	Carbonyl Sulfide, FTIR analysis 8/9/11 - SW	H040	3.0		
	005903633JJK			H111	1.0		
			Nitrogen Dioxide, FTIR analysis 11/02/11 - SW	H111	4.0		

Serial #	Manifest	Cylinder#	Receiving Notes	Mgt Cd	lbs	Disposal
845036	005903633JJK	110110CA26		H141	8.0	10/18/2011
845037	005903633JJK	110110CA30	Bad Valve - Blocked Port 08/16/11 - SW	H040	5.0	
			Trichlorosilane, drilled by DF, FTIR analysis 10/19/11 -			
			SW			10/19/2011
845038	005903633JJK	110110CA42	1,2-Dichlorodifluoroethylene (R1112), FTIR analysis	H040	3.0	
0.75000	000000000000000000000000000000000000000	4104100470	8/11/11 - SW	<u> </u>		9/13/2011
	005903633JJK			H141	1.0	10/19/2011
845040	005903633JJK	102910CA38	Bad Valve- Blocked port 8/17/11 - SW	H111	20.0	
			Hydrogen Sulfide, drilled by DF, FTIR analysis 10/24/11 - SW			11/11/2011
845041	005903633JJK	110110CA21	Empty, no liquid or pressure, nothing detected on H039 20.0		20.0	
			FTIR scan, valves on cylinder not completely seated.,			
L			FTIR analysis 8/10/11 - SW			8/11/2011
845042	005903633JJK	110110CA35	Diborane, FTIR analysis 8/18/11 - SW H040 20.0		20.0	8/26/2011
845043	005903633JJK	110110CA41	Carbon Tetrachloride, FTIR analysis 08/17/11 - SW	H061	20.0	8/17/2011
845044	005903633JJK	110110CA50	Bad Valve - Frozen Stem 8/18/11 - SW	H061	21.0	
			Dimethyl ether, drilled by DF, FTIR analysis 10/24/11 -			
			SW			10/24/2011
845045	005903633JJK	102710CA37	Empty, MS indicated atmosphere as contents,	H141	7.0	
			sampled by DF, FTIR/MS analysis 10/11/11 - SW	ļ		10/11/2011
845046	005903633JJK	102710CA39		H141		10/11/2011
	005903633JJK			H141	7.0	10/11/2011
845048	005903633JJK	102710CA45			7.0	10/11/2011
845049	005903633JJK	102710CA49	Hydrogen fluoride,, heavy liquid pH=0, thick pH=0	H111	4.0	
			white fumes when purging, KF deposit on cell window,			
			FTIR analysis ( confirmed by Bijan) 8/1/11 - SW			
						10/20/2011
845050	005903633JJK	102710CA53	Empty, no liquid or pressure, last contained NH3,	H039	4.0	
			CGA 110 valve assembly separated from cylinder due			
			to internal corrosion, 8/4/11- SW			8/1/2011
	005903633JJK		Propylene (propene), FTIR analysis 7/28/11 - SW	H061	4.0	8/1/2011
	005903633JJK		Propylene (propene) , FTIR analysis 7/27/11 - SW	H061	4.0	7/27/2011
845053	005903633JJK	102810CA46			5.0	
			contaminates detected, FTIR ( ATR) analysis 8/2/11 -			
			SW			8/2/2011
			Empty, no liquid or pressure, 8/2/11 - SW	H039	4.0	8/1/2011
845055	005903633JJK	102810CA54	Empty, No Pressure, Trace water, trace methane,	H039	4.0	
			H2O vapor, & CO2, FTIR analysis 7/28/11 - SW		]	
						8/1/2011
	005903633JJK			H141	4.0	8/1/2011
845057	005903633JJK	102810CA58	Empty, trace water, no pressure, FTIR analysis	H039	4.0	
			7/28/11 - SW			8/1/2011
845058	005903633JJK	102910CA06		H039	4.0	
			spectra), FTIR analysis, 8/4/11 - SW			8/11/2011
845059	005903633JJK	102910CA10	Empty, trace water, no pressure, FTIR analysis	H039	4.0	l
	<u>'</u>		7/28/11 - SW			8/1/2011
845060	005903633JJK	102910CA23	Dichlorodifluoromethane; CFC-12, FTIR analysis	H040	8.0	
<u></u>			8/9/11 - SW			8/16/2011
845061	005903633JJK	[110110CA07	Sent to Bijan for analysis WO:67387 BOL:081511-	H141	9.0	
<u></u>			8/15/11- SW			11/1/2011
			Methyl chloride, FTIR analysis 8/9/11 - SW	H040	6.0	8/16/2011
1845063	[005903633JJK	[110110CA18	Empty, No liquid or pressure, 7/28/11 - SW	H039	4.0	8/1/2011

Serial #	Manifest	Cylinder#	Receiving Notes	Disposal		
			Empty, no liquid or pressure, 08/10/11 - SW	Mgt Cd H039	12.0	8/11/2011
845065	005903633JJK		Bad Valve - Blocked Port 8/4/11 - SW	H039	·4.0	
			Empty, drilled by DF, FTIR analysis 10/18/11 - SW			
			Empty, no liquid or pressure, drilled by DF, FTIR			
			analysis 10/18/11 - SW			10/18/2011
845066	005903633JJK	102710CA25	Benzene, FTIR analysis 7/26/11 - SW	H061	2.0	7/26/2011
845067	005903633JJK			H040	1.0	8/26/2011
845068	005903633JJK	102910CA35	2,4,4-Trimethyl-1-pentene, FTIR analysis 8/16/11- SW	H040	5.0	
						8/16/2011
845069	005903633JJK	110110CA65		H121	50.0	5/24/2011
845070	005903633JJK	102710CA47	Trifluoromethyl hypofluorite, FTIR analysis 8/9/11 -	H111	3.0	
			SW			10/20/2011
	005903633JJK				3.0	12/7/2011
	005903633JJK		Dimethyl Ether, FTIR analysis 8/2/11 - SW	H040	4.0	8/12/2011
845073	005903633JJK	102810CA18	Bad Valve - CGA 110 Valve stem packing leak,	H039	3.0	
			2/22/11 - SW			
			Drilled by DF, Empty, no liquid or pressure, 40 psig			
			nitrogen pad added to get sample, Trace			
			Trimethylamine detected. FTIR analysis 5/11/11 - SW			
						5/11/2011
845074	005903633JJK	102810CA04	Nitrogen Dioxide ( Nitrosyl Chloride from NO2 and	H071	4.0	
			NaCl cell window reaction), +OX, slight orange-red			
			tint, cyl has liquid @ 5psig & 25C, Sodium Nitrate			-4
		1000100100	added to cell window, FTIR analysis 2/22/11 - SW	11404	20.0	5/17/2011
	005903633JJK			H121	39.0	
	005903633JJK		The base of the DE ETIDING and the 400000	H039	43.0	5/11/2011
845077	005903633JJK	102/10CA43	Fluorine, sampled by DF, FTIR/MS analysis 10/11/11 -  SW	Fluorine, sampled by DF, FTIR/MS analysis 10/11/11 - H111 7.		10/11/2011
845078	005903633JJK	102810CA03	Phosgene, drilled by DF, FTIR analysis 10/19/11 - SW	H111	4.0	10,1112011
0 10010		.020.00.00			,,,	10/19/2011
845079	005903633JJK	102910CA44	Hydrogen Sulfide, +S2, odor, HCl peaks possible	H103	4.0	
			nanifold contaminate from 811720, FTIR analysis			
			2/17/11 - SW			6/8/2011
845080	005903633JJK	102810CA34		H061	4.0	
845081	005903633JJK	102910CA39		H040	3.0	
845082	005903633JJK	<del></del>	Isobutane, FTIR analysis 8/3/11 - SW	H061	2.0	
845083	005903633JJK	102810CA47	Bad Valve - White crystaline solid blocking port.	H061	1.0	
			7/26/11 - SW			
			Methylsilane, drilled by DF, FTIR analysis 10/19/11 -			
			SW			10/19/2011
845084	005903633JJK	102810CA48	Bad Valve - Frozen Stem 08/16/11 - SW	H061	7.0	
1			Methyl Chloride, drilled by DF, FTIR analysis 10/19/11	1	ĺ	
			SW			10/19/2011
	005903633JJK			H040	1.0	
845086	005903633JJK	110110CA09	Empty, no liquid or pressure, N2 added to get sample,	H039	12.0	
			residual check negative, FTIR analysis 8/17/11 - SW			
				11151	<u> </u>	8/17/2011
845087	005903633JJK	1	Unable to determine contents 8/16/11 - SW	H121		11/3/2011
845088	005903633JJK	102910CA37	Nitrogen Dioxide (family), sampled by DF, FTIR	H111	3.0	
0.450.00	100000000000000000000000000000000000000	1000100110	analysis 11/02/11 - SW	114.44		11/3/2011
845089	005903633JJK	1102910CA40		H141	3.0	11/3/2011

	Manifest	Cylinder #	Receiving Notes	Mgt Cd		Disposal
845090	005903633JJK	110110CA46	Chloromethane ( Methyl chloride), FTIR analysis 2/22/11 - SW	H039	3.0	4/20/2011
845091	005903633JJK	102910CA25		H061	8.0	9/8/2011
	005903633JJK		Bad Valve - Frozen Stem - 8/04/11 - SW	H040	8.0	0/0/2011
0.0002		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Methyl Chloride, drilled by Stan, FTIR analysis 9/13/11		0.0	
			- SW			9/13/2011
845093	005903633JJK	110110CA47		H040	8.0	7/5/2011
	005903633JJK		Ethylene, drilled by Stan, FTIR analysis 9/13/11 - SW	H061	8.0	
					•	9/13/2011
845095	005903633JJK	110110CA56	Methyl Chloride, drilled by Stan, FTIR analysis 9/13/11	H040	9.0	
			- SW			9/13/2011
845096	005903633JJK	102810CA12	Nitrogen Dioxide (nitric oxide, nitrous oxide, and	H071	3.0	
			nitrogen dioxide peaks detected), light orange-red tint			
			in cell,+OX, sodium nitrate deposited on cell window,			
	and the state of t		pressure @ 0 psig @ 17C, unable to detect if liquid in			
			cyl. , FTIR analysis 2/22/11 - SW			5/17/2011
	005903633JJK			H039	80.0	8/22/2011
		102710CA40		H111	4.0	10/19/2011
		102810CA43	Ethylene Oxide, FTIR analysis, 2/22/11 - SW	H040	H040 2.0 4/8/20	
		110110CA63		H132	100.0	6/20/2011
845101	005903633JJK	102910CA15	Silane, FTIR analysis 8/3/11 - SW H132		3.0	8/3/2011
845102	005903633JJK	102810CA44	Sulfur tetrafluoride/ thionyl fluoride, FTIR analysis H121		4.0	9/27/2011
845103	005903633JJK	110110CA06	Thionyl Fluoride, FTIR analysis 7/27/11 - SW	H111	2.0	9/26/2011
	005903633JJK			H040	1.0	12/27/2010
845105	005903633JJK	102910CA43		H040	1.0	7/7/2011
845106	005903633JJK	110110CA23	Empty, no liquid or pressure, vinyl bromide not deteted H039 on FTIR scan, N2 added to get sample, FTIR analysis		4.0	8/2/2011
045407	005903633JJK	1120100001	8/2/11 - SW	H039	28.0	12/7/2010
	005903633JJK			H039	28.0	12/7/2010
845109	005903633JJK		No pressure with liquid, Nothing detected by FTIR	H039	28.0	12///2010
040100	00030000000	1100100700	scan, PRTC, FTIR analysis 3/21/11 - SW	11000	20.0	3/21/2011
845110	005903633JJK	113010CA04	Journal of Fritterial you of Elife Off	H039	29.0	12/7/2010
	005903633JJK			H039	29.0	
	005903633JJK			H039	29.0	12/7/2010
	005903633JJK			H039	29.0	12/8/2010
	005903634JJK	<del></del>	Acrolein, Carbon Monoxide, methane and aliphatic	H141	3.0	
0 10 10 1		10201007110	hydrocarbons detected, FTIR analysis 2/17/11 - SW		0.0	9/1/2011
845485	005903634JJK	110110CA25	Empty, no liquid or pressure, Acrolein not detected,	H039	3.0	
040400	000000000000000000000000000000000000000	1101100120	trace methyl chloride detected in initial scan, FTIR analysis 7/26/11 - SW	11000	0.0	
045406	005002624111/	1027100 446		<b>□</b> 444	4.0	7/26/2011
845486	005903634JJK	11021 100A 18	Hydrogen Bromide, FTIR analysis 11/02/11 - SW	H111	4.0	11/3/2011

# MANAGEMENT METHOD CODES

Management Method codes describe the type of hazardous waste management system used to treat or dispose a hazardous waste. The Final Management Method AT THIS SITE (on GM Section 4, the final management at the facility the waste was shipped to).

	Reclamation and Recovery
H010	Metals recovery including retorting, smelting, chemical, etc.
H020	Solvents recovery (distillation, extraction, etc)
Н039	Other recovery or reclamation for reuse including acid regeneration, organics recovery, etc. (specify in comments)
H050	Energy recovery at this site – use as fuel (includes on-site fuel blending before fuel burning at this site –
******	report both as one H050 method) [This site burns the waste as a fuel substitute, usually a cement kiln.]
H061	Fuel blending prior to energy recovery at another site [This means this site did not burn the waste as a fuel
	substitute, but blended it to specification for burning at a different site.]
	Destruction or Treatment (Prior to Disposal of Residuals at Another Site)
H040	Incineration - thermal destruction other than use as a fuel (included preparation prior to burning) [This
	means the site is a commercial hazardous waste incinerator. DO NOT USE this code if the waste is blended
*1684	or burned as a fuel substitute.]
H071	Chemical reduction with or without precipitation (includes any preparation or final processes for
11092	consolidation of residuals)  Cyanide destruction with or without precipitation (includes any preparation or final processes for
Н073	
H075	consolidation of residuals)  Chemical oxidation (includes any preparation or final processes for consolidation of residuals)
H076	Wet air oxidation (includes any preparation or final processes for consolidation of residuals)
H077	Other chemical precipitation with or without pre-treatment (includes any preparation or final processes for
	consolidation of residuals)
H081	Biological treatment with or without precipitation (includes any preparation or final processes for consolidation of residuals)
H082	Adsorption (as the major component of treatment)
H083	Air or steam stripping (as the major component of treatment)
H101	Sludge treatment and/or dewatering (as the major component of treatment - not H071-H083)
H103	Absorption (as the major component of treatment – not H071-H083)
HIII	Stabilization or chemical fixation prior to disposal at another site (as the major component of treatment - not H071-H083)
H112	Macro-encapsulation prior to disposal at another site (as major component of treatment - not H071-H083)
H121	Neutralization only (NO other treatment)
H122	Evaporation (as the major component of treatment not H071-H083)
H123	Settling or clarification (as the major component of treatment - not H071-H083)
H124	Phase separation (as the major component of treatment - not H071-H083)
H129	Other treatment (specify in comments - not described by any other code)
	Disposal
H131	Land treatment or application (includes any treatment and/or stabilization prior to disposal at this facility)
H132	Landfill or surface impoundment that will be closed as landfill (to include any treatment and/or stabilization
	at this facility)
H134	Deepwell or underground injection (with or without treatment)
H135	Discharge to sewer/POTW or NPDES (with prior storage regulated by RCRA - with or without treatment)
	Storage and Transfer
Hi41	Storage, bulking, and/or transfer off site – no treatment/recovery (H010-H129), fuel blending (H061), or disposal (H131-H135) at this site [Do not use in the on-site section of Form GM.] Linked to source code G61 on Form GM.
	On Che Camera Souther Outs in Castley A - Chamera
11145	On-Site Storage - for Use Only in Section 3 of Form GM
H142	Waste stored at Year End and for more than 90 days that was generated this reporting year
H143	Wasto stored at Year End that was generated prior to this reporting year



#### GAS CYLINDER PROPOSAL FOR Environmental Quality Management Project for Cadle Auto Jeff Rhinefield November 15, 2010

Scope of Work: SET Environmental to send a cylinder specialist and driver to pick-up and pack the cylinders listed below and properly treat and dispose of them. Testing will be done on all unknown cylinders at our labs in Houston, Texas to determine contents, there will not be any testing done on-site. Pricing below reflects costs for all disposal, services, equipment and transportation.

Size	Rate	Field ID	Suspected Contents
lecture	\$100.00	102710CA001	Ammonia
lecture	\$100.00	102710CA002	Ammonia, Anhydrous
lecture	\$100.00	102710CA003	Sulphur Hexafluoride
łecture	\$100.00	102710CA004	Unknown Suspected: Boron Trichloride
lecture	\$525.00	1027 10CA005	Trimethyl Aluminum
lecture	\$325,00	102710CA006	Trifluoroacetyl Fluoride
lecture	\$525.00	102710CA007	Triethyl Aluminum
lecture	\$525.00	102710CA008	Tri Isobutlyl Aluminum
Small	\$175.00	1027 10CA009	Ammonia, Anhydrous
Grill	\$1,000.00	102710CA010	Triethylborane

Small	\$795.00	102710CA01 1	Unknown Suspected: Diethyl Aluminum Hydride
lecture	\$525.00	102710CA012	Diethyl Zinc
Small	\$795.00	102710CA013	Trimethyl Aluminum
lecture	\$525.00	102710ÇA014	Di isobutyi Aluminum Hydride
lecture	\$525,00	102710CA015	Triethyl Aluminum
lecture	\$900.00	102710CA016	Unknown Suspected: Bromine Pentafluoride
lecture	\$525.00	102710CA017	Triethyl Aluminum
lecture	\$100.00	102710CA018	Corrosive Liquid
lecture	\$525.00	102710CA019	Tetraethyitin
lecture	\$525.00	1027 10CA020	Di Isobutyi Aluminum Hydride
lecture	\$1,000.00	102710CA021	Unknown
lecture	\$300.00	1027100A022	Vanadium (V) Trichloride Oxide
small	\$175.00	1027 10CA023	Unknown Suspected: Ammonia
medium	\$1,500.00	1027 10CA024	Trì Isobutyl Aluminum
fecture	\$1,000.00	1027 10CA025	Unknown

•

lecture	\$525.00	1027 10CA026	Unknown Suspected: Triethyl Borane
lecture	\$100.00	1027 10CA027	Unknown Suspected: Chlorine
lecture	\$525.00	1027 10CA028	Unknown Suspected: Triethyl Borane
lecture	\$100.00	102710CA029	Unknown Suspected: Ammonia
lecture	\$525.00	102710CA030	Unknown Suspected: Triethyl Borane
lecture	\$100.00	102710CA031	Vanadium Oxytrichloride
Tecture	\$100.00	102710CA032	Unknown Suspected: Boron Trichloride
lecture	\$1,000.00	102710CA033	Unknown
lecture	\$525.00	1027 10CA034	Unknown Suspected: Fluoromethyl Sulfide Compound
lecture	\$100.00	102710CA035	Unknown Suspected: Ammonia
lecture	\$1,000.00	102710CA036	Unknown
small	\$1,500.00	102710CA037	Unknown
lecture	\$140.00	102710CA038	Unknown Suspected: 1,3- Butadiene
small	\$1,500.00	102710CA039	Unknown
small	\$600.00	1027 10CA040	Perchloryl Fluoride
small		102710CA041	Unknown

	\$1,500.00		
lecture	\$1,000,00	1027 10CA042	Unknown
small	\$1,300.00	1027 10CA043	Unknown Suspected: Fluorine (HW)
lecture	\$1,000.00	102710CA044	Unknown
small	\$1,500.00	1027 10CA045	Unknown
lecture	\$1,000.00	102710CA046	Unknown
lecture	\$1,000.00	1027 10CA047	Unknown
lecture	\$1,000.00	.1027 10CA048	Unknown
small	\$1,500.00	1027 10CA049	Unknown
lecture	\$750.00	1027 10CA050	Unknown Suspected: Chloropentafluoroethane
small	\$400.00	102710CA051	Trifluoroethylene
lecture	\$1,000.00	102710CA052	Unknown
lecture	\$100.00	1027 10CA053	Unknown Suspected: Ammonia & Methylamine
lecture	\$1,000.00	102710CA054	Unknown
lecture	\$1,000.00	102710CA055	Unknown
lecture	\$1,000.00	102710CA056	Unknown

lectur <b>e</b>	\$1,000.00	102710CA057	Unknown
lecture	\$1,000.00	102710CA058	Unknown
lecture	\$100,00	102710CA059	Unknown Suspected: Hydrogen Chloride
lecture	\$1,000.00	1027 10CA060	Unknown
lecture	\$1,000.00	102710CA061	Unknown
lecture	\$525.00	102810CA001	Unknown Suspected: Pyrophoric Liquid
lecture	\$1,000.00	1028 10CA002	Unknown
lecture	\$525.00	1028 10CA003	Unknown Suspected: Hydrogen Selenide
lecture	\$525.00	1028 10CA004	Unknown Suspected: Nitrosyl Chloride (SET- either Nitric Oxide or Nitrogen Dioxide)
lecture	\$100.00	102810CA005	Unknown Suspected: Hydrogen Chloride
lecture	\$1,000.00	102810CA006	Unknown CF3 SAg
small	\$1,000.00	102810CA007	Unknown
lecture	\$525.00	1020 10CA008	Tri Isobulyi Aluminum
small	\$1,500.00	102810CA009	Unknown
lecture	\$140.00	102810CA010	Unknown Suspected: Dimethyl
lecture	\$1,000.00	102810CA011	Unknown

	lecture	\$575.00	102810CA012	Unknown Suspected: Nitirc Oxide/Nitrous Oxide (Change ou brass outlet cap to SS cap)
***************************************	lecture	\$1,000.00	102810CA013	Unknown
	lecture	\$100.00	102810CA014	Unknown Suspected: Chlorine <sup>Gas</sup>
	lecture	\$1,000.00	102810CA015	Unknown
	lecture	\$100.00	102810CA016	Unknown Suspected: Boron Trichloride
	lecture	\$1,000.00	102810CA017	Unknown
l. r	lecture	\$100.00	1028 10CA018	Unknown Suspected: Dimethylamine
	lecture	\$525.00	1028 10CA019	Unknown Suspected: Acrolein w/Nitrogen and Helium
	lecture	\$1,000.00	102810CA020	Unknown
1	lecture	\$300.00	102810CA021	Vanadium Tetrachloride 90%
	lecture	\$300.00	1028 10CA022	Vanadium Tetrachloride
1	lecture	\$300.00	1028 10CA023	Vanadium Tetrachloride
	lecture	\$300.00	102810CA024	Unknown Suspected: Vanadium Tetrachloride
	lecture	\$300.00	1028 10CA025	Unknown Suspected: Hydrogen &
1	lecture	\$1,000.00	102810CA026	Change to Suspect 2.3 (8) can not be Ammonia: Valve appears to be other than stainless or carbon steel. Monel Packing nut & ASB/Monel outlet cap
			102810CA027	Vanadium Oxytrichloride

lecture	\$300.00	Terret	
lecture	\$1,000.00	1028 10GA028	Unknown
lecture	\$1,000.00	102810CA029	Unknown
lecture	\$300.00	102810CA030	Unknown Suspected: Vanadium Trichloride
lecture	\$1,000.00	102810CA031	Unknown
lecture	\$300.00	1028 10CA032	Hexafluoroacetone
lecture	\$1,000.00	102810CA033	Unknown
lecture	\$110.00	102810CA034	Unknown Suspected: Isobutane
small	\$1,500.00	102810CA035	Unknown
small	\$500.00	102810CA036	Dodecyl Mercaptan
small	\$175.00	102810CA037	Ammonia, Anhydrous
small	\$200.00	102810CA038	Unknown Suspected: Flammable Gas
lecture	\$525.00	102810GA039	Unknown Suspected: Pyrophoric
small ,	\$500.00	102810CA040	Dodecyl Mercapian
medium	\$1,850.00	102810CA041	Unknown
small	\$1,500.00	102810CA042	Unknown
lecture	\$575.00	102810CA043	Unknown Suspected: Phosgene

lecture	\$575.00	1028 10CA044	Unknown Susected: Sulfur pl Tetrafluoride
lecture	\$575.00	1028 10CA045	Trichlorosilane
small	\$1,500.00	1028 10CA046	Unknown
lecture	\$575.00	1028 10CA047	Unknown Suspected: Vinyi Silane
small	\$1,500.00	102810CA048	Unknown
small	\$1,500.00	102810CA049	Unknown
lecture	\$100.00	102810CA050	Unknown Suspected: Ammonia
lecture	\$300.00	102810CA051	Hexafluoroacetone
small	\$1,500.00	102810CA052	Unknown
small	\$1,500.00	102810CA053	Unknown
small	\$1,500.00	102810GA054	Unknown
small	\$1,500.00	102810CA055	Unknown
lecture	\$525.00	102810CA056	Unknown Suspected: 1,2,1,2 Tetrafluoroethylene sulfonyl fluoride
small	\$575.00	1028 10CA057	Unknown Suspected: Trichlorosilane (HW)
small	\$1,500.00	1028 10CA058	Unknown
small	\$790.00	1028 10CA059	Unknown Suspected: Trichlorosilane (HW)

		1	I
medium	\$1,200,00	102810CA060	Unknown Suspected: Triethyl Borane
medium	\$1,200.00	1029 10CA001	Triethyl Aluminum
lecture	\$100.00	102910CA002	Unknown Suspected: Ammonia
lecture	\$525.00	102910CA003	Unknown Suspected: Dimethyl Aluminum Hydride
la aluan	¢505 00	102910GA004	Diethyl Aluminum Chloride
lecture medium	\$525.00	1029 10CA005	Triethyl Aluminum
small	\$1,200.00 \$1,500.00	102910CA006	Unknown
lecture	\$525.00	1029 10CA007	Triethyl Aluminum
lecture	\$1,000.00	1029 10CA008	Unknown
lecture	\$525.00	1029 10CA009	Unknown Suspected: Methyl Magnesium Chloride in
small	\$1,500.00	102910CA010	Unknown
Jecture	\$625,00	102910CA011	Dimethyl Cadmium (HW)
lecture	\$625.00	1029 10CA012	Unknown Suspected: Triffuoroethyl Fluoride
lecture	\$150.00	1029 10CA013	Unknown Suspected: Pyrethin and Freon 12
lecture	\$300.00	1029 10CA014	Trifluoroacetyl Chloride
lecture	\$575.00	1029 10CA015	Unknown Suspected: Silane
lecture	\$450.00	1029 10CA016	Unknown Suspected: Chloropierin and Methyl Bromide

A 117-40-4-1-4-1-4-1-4-1-4-1-4-1-4-1-4-1-4-1-			
small	\$600.00	102910CA017	Unknown Suspected: Pasticide
lecture	\$500.00	102910CA018	Unknown Suspected: Parthion in Acetone w/Chloromethane
small	\$1,500.00	1029 10CA019	Unknown Suspected: Solution of Chlorine in Bromine
small	\$1,500.00	1029 10CA020	Unknown
lecture	\$500.00	102910GA021	Unknown Suspected: Chloropierin and Methyl Bromide
meduim	\$2,000.00	102910CA022	Fluorina
small	\$1,500.00	1029 10CA023	Unknown
medium	\$575.00	102910CA024	Freon 116
small	\$200.00	102910CA025	Unknown Suspected: Chloromethane
medlum	\$1,875.00	102910CA026	Unknown
lecture	\$55.00	102910CA027	Unknown Suspected; Nitrogen and Oxygen
Small	\$140.00	102910CA028	Unknown Suspected: Molybdenum Hexafluoride
Small	\$100.00	102910CA029	Chlorine
4,31" x 13.5"	\$925.00	102910CA030	Flammable Gas Per Dean - Bromine Chloride, en though this has a 2.1 diamond label on it
4.29" x 14"		102910CA031	Unknown Suspected: Propane, Hydrogen Sulfide, Carbon

	\$300.00		Dioxide, Methane
2" x 12.9"	\$1,000.00	102910CA032	Unknown
medium	. \$200.00	102910CA033	Unknown Suspected: Non- Flammable Gas
medium .	\$1,875.00	102910CA034	Unknown Suspected: Toxic Gas
small	\$1,500.00	102910GA035	Unknown
lecture	\$140.00	102910CA036	Unknown Suspected: Hydrogen Methane
lecture	\$1,200.00	102910CA037	Unknown Money Cylinder with Monel Valve) Suspected: Ar/Cr02l2 (HW)
medium	\$1,875.00	102910CA038	Unknown
lecture	\$110.00	102910CA039	Isobutane
lecture	\$1,200.00	1029 10CA040	Unknown (Monel cylinder with Monel valve)
lecture	\$525.00	102910ÇA041	Unknown Suspected: Methanethiol/Dimethyl Sulfide
medlum	\$2,000.00	1029 10CA042	Fluorine
lecture	\$100.00	102910CA043	Trimethylamine, Anhydrous
lecture	\$525,00	1029 10CA044	Hydrogen Sulfide
lecture	\$110.00	10291DCA045	1-Bromo-1,1- Difluoropropene-2
lecture	\$500.00	1101 10CA001	Unknown Suspected: Pyrophoric
lecture	\$300.00	1101110CA00 2	Unknown Suspected: Hydrogen Bromide
medlum		110110CA003	Unknown

·	\$1,875.00	<b></b>	
lecture	\$925.00	1101 10CA004	Unknown Suspected: Chlorine Trifluoride
lecture	\$525.00	11011100A005	Unknown Suspected: Pyrophoric TMA
lecture	\$575,00	11011160A008	Unknown Suspected: Sulfur Tetrafluoride
small	\$1,500.00	110110CA007	Unknown
lecture	\$100.00	110119CA008	Unknown Suspected: Chlorine
small	\$1,500.00	110110GA009	Unknown
lecture	\$300.00	1101 10CA010	Unknown Suspected: Hydrogen Bromlde
lecture	\$525.00	1101 10CA01 1	Unknown Suspected: Pyrophoric Aluminum Alkyls
lecture	\$1,000.00	110110CA012	Unknown
lecture	\$1,000.00	110111CA013	Unknown NEED LECTURE OP
small	\$150.00	1101110CA01 4	Sulfur Hexafluoride
lecture	\$1,000.00	110110CA015	Unknown NEED ANY SALVAGE VESSEL
<b>fecture</b>	\$1,000.00	110110CA016	Unknown
small	\$1,500.00	110110CA017	Unknown
emall	\$1,500,00	110110CA018	Unknown
small	\$1,600.00	110110CA019	Unknown
lecture	\$300,00	110110CA020	Trifluoromethane Sulfonyl Chloride
2".38" x 24.75"	\$2,000.00	110110CA021	Unknown

lecture	\$1,000.00	110110CA022	Unknown
lecture	\$575.00	1101 10CA023	Unknown Suspecied: Vinyl Bromide
lecture	\$1,000.00	110110CA024	Unknown ·
lecture	\$925.00	1101 10CA025	Unknown Suspected: Acrolein
lecture	\$1,000.00	110110CA026	Unknown
lecture	\$1,000.00	1101 10CA027	Unknown
lecture	\$300.00	1101 10CA028	Vanadium Tetrachloride
small	\$1,500.00	110110CA029	Unknown
lecture	\$1,000.00	110110CA030	Unknown
lecture	\$300.00	1101 10CA03 1	Vanadium Tetrachloride
lecture	\$1,000.00	110110CA032	Unknown
lecture	\$300.00	1101 10CA033	Vanadium Oxy Trichloride
lecture	\$100.00	1101 10CA034	Sulfer Dioxide
medium	\$2,200.00	110110CA035	Unknown
lecture	\$100.00	1101 10CA036	Sulfer Dioxide
lecture	\$300.00	1101 10CA037	Vanadium Tetrachloride
lecture	\$1,000.00	110110CA038	Unknown
lecture	\$100.00	1101 10CA039	Sulfer Dioxide, anhydrous

		]	l .
lecture	\$140:00	1101 10CA040	Unknown flammable gas
medium	\$2,200.00	110110CA041	Unknown
leoture	\$1,000.00	1101 10CA042	Unknown
small	\$140.00	110110CA043:	Chloromethane
lecture	\$140.00	110110CA044	Hydrogen lodide
spud	\$125.00	1101 10CA045	Dichlorodifluoromethane
lecture	\$100.00	110110CA046	Chloromethane
small	\$150.00	1101 10CA047	Chloromethane
55gallon	\$1,500.00	110110CA048	Mercury
small	\$300.00	110110CA049	Hydrofluoric Acid, anhydrous
medium	\$2,200.00	1101 10CA050	Unknowns
medium	\$425.00	1101 10CA051	Chlorine, high purity
large	\$600.00	1101 10CA052	Chlorine
small	\$300.00	110110CA053	Chloromethane
large	\$600.00	1101 10CA054	Chlorine
medium		110110CA065	Acetylene

•

	\$100.00		
small	\$300.00	110110CA056	Chloromethane
lecture	\$100.00	1101 10CA071	Hydrogen Chloride ·
lecture	\$1,000.00	1101 10DA072	Unknown
lecture	\$100.00	1101 10CA073	Chlorine
lecture	\$100.00	1101 10CA074	Chlorine gas NON_DOT
lecture	\$100.00	1101 10CA075	Hydrogen Chloride NON DOT
small	\$300.00	111 1A 0 0C 076	Vanadium Oxy Trichloride
lecture	\$100.00	110110CA077	Hydrogen Chloride NON DOT
small	\$1,500.00	1101 10CA078	Unknown NON DOT
lecture	\$300.00	1101 10CA079	Vanadium Oxy Trichloride

## Total cost summary for project:

Disposal	\$170,120.00	
Confirmation Fees (74)	\$9,250,00	
Inoperable Valve (50)	\$5,000.00	
Mobilization	\$1,000.00	
Cylinder Specialist	\$1,750.00	
Cylinder Technician	\$950.00	
Per Diem	\$575.00	
Salvage Vessels		
LP (6)	\$400.00	
Lecture packs (4)	\$2,000.00	
Transportation	\$2,900.00	
Transportation	\$850.00	
Supplies	\$300.00	
Subtotal	\$195,095.00	
Recovery 7%	\$13,656.65	
State Waste Fee	\$200,00	
Estimated Total	\$208,951.65	